View NSN Online: https://aerobasegroup.com/nsn/8030-00-252-8300

CASTROL INC, BRAY PRODUCTS DIV. -- BRAYCOTE 120 -- 8030-00-252-8300

Product ID:BRAYCOTE 120 MSDS Date:11/12/1997

FSC:8030

NIIN:00-252-8300

MSDS Number: CGNDG === Responsible Party ===

Company Name: CASTROL INC, BRAY PRODUCTS DIV.

Address:1001 WEST 31ST STREET

City: DOWNERS GROVE

State:IL

ZIP:60515-1280 Country:US

Info Phone Num:800-621-2661 Emergency Phone Num:800

-424-9300

CAGE:KO468

=== Contractor Identification ===

Company Name: CASTROL INC, BRAY PRODUCTS DIV.

Address:16715 VON KARMAN AVE., SUITE230

Box:City:IRVINE

State:CA ZIP:92714 Country:US

Phone:714-660-9414

CAGE:KO468

Company Name: CASTROL INDUSTRIAL NORTH AMERICA INC SPECIALTY PRODUCTS

DIV

Address:1001 WEST 31ST STREET

Box:City:DOWNERS GROVE

State:IL

ZIP:60515-1280 Country:US

Phone: 800-621-2661/FAX: 630-241-4140

CAGE:2R128

======= Composition/Information on Ingredients ========

Ingred Name: DISTILLATES CAS:64742-54-7 RTECS #:PY8035500 Fraction by Wt: 10-15% Other REC Limits: NONE RECOMMENDED OSHA PEL:5 MG/M3 ACGIH TLV:5 MG/M3 Ingred Name: SOLVENT NAPHTHA CAS:64742-88-7 Fraction by Wt: 20-25% Other REC Limits: NONE RECOMMENDED OSHA PEL:435 MG/M3 ACGIH TLV:435 MG/M3 ========== Hazards Identification =============== Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chron ic:EYE: IRRITATION. SKIN: IRRITATION. INHAL: IRRITATION, RESPIRATORY TRACT DAMAGE. INGEST: GI DISTRESS, NAUSEA, VOMIT, DIARRHEA, ABDOMINAL PAIN. First Aid:EYE: FLUSH W/WATER FOR 15 MIN. SKIN: WASH W/SOAP & WATER. REMOVE CONTAM CLOTHES. WASH BEFORE REUSE. USE SKIN CREAM FOR DEFATTED AREA. INHAL: GET FRESH AIR. ARTIF RESP IF NEEDED. KEEP PERSON WARM & AT REST. INGEST: ASPIRATION HAZARD. DONT INDUCE T OR GIVE ANYTHING BY MOUTH. DONT LEAVE UNATTENDED. IF VOMIT OCCURS OR COMA, LATHARGIC, PLACE ON LEFT SIDE W/HEAD DOWN. IN ALL CASES, GET MED AID.

========== Fire Fighting Measures ===============

Flash Point Method:PMCC Flash Point:>100F,>38C

Extinguishing Media:WATER, DRY CHEMICAL, CO2 OR ALCOHOL FOAM.

Fire Fighting Procedures:WATER OR FOAM MAY CAUSE FROTHING. USE WATER TO COOL CONTAINERS. FLUSH SPILLS W/WATER SPRAY. USE SCBA. PREVENT RUNOFF TO STEAMS OR DR

INKING WATER SUPLIES. Unusual Fire/Explosion Hazard:HAZARDOUS PRODUCT OF COMBUSTION: IRRITATING/TOXIC FUMES: CO & CO2.
========= Accidental Release Measures ==========
Spill Release Procedures:LGSP: USE PROTECTIVE CLOTHES. STOP LEAK, DIKE. CONTAINERIZE & RECOVER FREE LIQUID. PREVENT ENTRY INTO WATERWAYS. SOAK UP RESIDUE W/ISUITABLE INERT ABSORBENT STORE & DISPOSE OF PROPERLY. FLUSH AREA W/W ATER WHERE FEASIBLE/APPROPRIATE.*
=========== Handling an d Storage ====================================
Handling and Storage Precautions:MAINTAIN ABUNDANT TEMPS. KEEP CONTAINERS TIGHTLY CLOSED. DONT STORE NEAR HEAT, FLAME, STRONG OXIDANTS. MAINTAIN ADEQUATE VENT.
====== Exposure Controls/Personal Protection ========
Respiratory Protection:USE NIOSH/MSHA APPROVED RESPIRATOR W/ORGANIC VAPOR CARTRIDGE IF VAPOR CONCENTRATIONS EXCEED PERMISSIBLE EXPOSURE LIMITS.
Ventilation:MECHANICAL (GENERAL) OR LOCAL EXHAUST TO MAINTAIN EXPOSURE
BELOW TLV. >60F3/MIN RECOMMENDED. Protective Gloves:SOLVENT RESISTANT Eye Protection:CHEMICAL SAFETY GLASSES/SIDE SHIELDS Other Protective Equipment:IMPERVIOUS PROTECTIVE CLOTHING & CHEMICAL RESISTANT SAFETY SHOES. EMERGENCY SHOWER & EYEWASH FACILITY. Work Hygienic Practices:WASH CONTAM CLOTHES W/SOAP & WATER, DRY BEFORE REUSE. DONT WEAR CONTACT LENSES. Supplemental Safety and Health *REMOVE CONTAM SOIL. SMLSP: NEUTRALIZE AND/OR SOAK UP SPILL W/INERT ABSORBENT. STORE IN A CLOSED CONT
========= Physical/Chemical Properties ==========
Boiling Pt:B.P. Text:240F,116C Vapor Density:3.5 Spec Gravity:0.8700 pH:NA Viscosity:NA Evaporation Rate & Deference:0.33 Solubility in Water:COMPLETE Appearance and Odor:AMBER LIQUID, CHARACTERISTIC SOLVENT ODOR. Percent Volatiles by Volume:65.0
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES NK Stability Condition to Avoid:STRON

G OXIDIZING AGENTS.
Hazardous Decomposition Products:IRRITATING OR TOXIC FUMES, CO & CO2.

====== Disposal Considerations ===========

Waste Disposal Methods:EPA D-001. DISPOSE OF IN ACCORDANCE W/FEDERAL, STATE & LOCAL REGULATIONS. DISPOSAL OF THIS MATERIAL TO LAND MAY BE BANED BY FEDERAL LAW.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United Stat es of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.