Product ID: HP LASER JET CARTRIDGE C3906A MSDS Date:01/16/1996 FSC:6850 NIIN:01-428-3583 Status Code:A MSDS Number: CJCWV === Responsible Party === Company Name: HEWLETT-PACKARD CO BOISE DIV Address:11311 CHINDEN BLVD City:BOISE State:ID ZIP:83714 Country:US Info Phone Num:208-396-6000/323-2551 Emergency Phone Num:208-396-6000/323-2551 CAGE:1866 0 === Contractor Identification === Company Name: HEWLETT-PACKARD CO BOISE DIV Address:11311 CHINDEN BLVD Box:City:BOISE State:ID ZIP:83714 Country:US Phone:208-396-6000 CAGE:18660 Company Name: ODYSSEY GROUP THE Address:245 LOCHAN CV STE B18 Box:000 **City:ALPHARETTA** State:GA ZIP:30202-7614 Country:US Phone:800-250-8716/FAX 770-754-1194 Contract Num:SP0450-98-M-CJ31 CAGE:05NL2

Ingred Name:STYRENE ACRYLATE COPOLYMER, CAS:25153-4

6-2 Minumum % Wt:45. Maxumum % Wt:55.

Ingred Name:IRON OXIDE CAS:1317-61-9 Minumum % Wt:45. Maxumum % Wt:55. OSHA PEL:10 MG/M3 ACGIH TLV:5 MG/M3

LD50 LC50 Mixture:LD50 (ORAL RAT) IS >5000 MG/M3 Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:MAY CAUSE EYE IRRITATION. UNLIKELY TO CAUSE SKIN IRRITATION. MINIMAL RESPIRATORY TRACT IRR ITATION MAY OCCUR AS WITH EXPOSURE TO LARGE AMOUNTS OF ANY TOXIC DUST. INGESTION IS NOT APPLICABLE ROUTE OF EN TRY FOR INTENDED USE. Explanation of Carcinogenicity:MANUFACTURER GAVE NO INFORMATION ABOUT CARCINOGENICITY. HMIS DOES NOT EXPECT IT TO BE CARCINOGENIC. Effects of Overexposure:EYES-IRRITATION. INHALED-MINIMAL RESPIRATORY

IRRITATION.

Medical Cond Aggravated by Exposure:MFR GAVE NO INFORMATION ON MSDS.

First Aid:INGESTED-DILUTE STOMACH CONTENTS WITH SEVERAL GLASSES OF WATER. IF SYMPTOMS OCCUR, CONSULT A PHYSICIAN. INHALED-REMOVE VICTIM TO FRESH AIR. IF SYMPTOMS OCCUR, CONSULT A PHYSICIAN. EYES-FLUSH WITH RUNN ING WATER FOR AT LEAST 15 MINUTES, IF SYMPTOMS OCCUR, CONSULT A PHYSICIAN. SKIN-WASH WITH SOAP & WATER. IF SYMPTOMS OCCUR, CONSULT A PHYSICIAN.

Extinguishing Media:WATER, DRY CHEMICAL, CO2 Fire Fig

hting Procedures:NONE. Unusual Fire/Explosion Hazard:TONER MATERIAL LIKE MOST ORGANIC MATERIAL IN POWDER FORM, IS CAPABLE OF CREATING A DUST EXPLOSION.

Spill Release Procedures:WEAR PERSONAL PROTECTIVE EQUIPMENT AS DESCRIBED. MINIMIZE THE RELEASE OF PARTICULATES. VACUUM OR SWEEP THE MATERIAL INTO A BAG OR OTHER SEALED CONTAINER AND DISPOSE OF IN ACCORDANCE WITH LOCAL REQUIRE MENTS. DO NOT DISCHARGE INTO DRAINS.

Neutralizing Agent:MFR GAVE NO INFORMATION ON MSDS.

Handling and Storage Precautions: KEEP OUT OF REACH OF CHILDREN. KEEP FROM CONTACT WITH OXIDIZING MATERIALS. KEEP CONTAINER CLOSED AND STORE AT ROOM TEMPERATURE. AVOID INHALATION OF DUST AND CONTACT WITH EYES. KEEP AWAY FROM EXCESSIVE HEAT, SPARKS, AND OPEN FLAMES. Other Precautions: NONE SPECIFIED BY MANUFACTURER.

====== Exposure Controls/Personal Protec

tion ==================

Respiratory Protection:NONE REQUIRED UNDER INTENDED USE.

Ventilation: GOOD GENERAL VENTILATION SHOULD BE SUFFICIENT UNDER INTENDED USE.

Protective Gloves: NONE REQUIRED UNDER INTENDED USE.

Eye Protection: NONE REQUIRED UNDER INTENDED USE.

Other Protective Equipment:NONE REQUIRED UNDER INTENDED USE.

Work Hygienic Practices: DLA-HMIS FOCAL POINT: USE GOOD INDUSTRIAL

HYGIENE PRACTICE. AVOID UNNECESSARY CONTACT. WASH THOROUGHLY AFTER HANDLING.

Supplemental Safety and Hea Ith

HCC:N1 NRC/State Lic Num:NONE Melt/Freeze Pt: