View NSN Online: https://aerobasegroup.com/nsn/5910-01-019-8871

Product ID: POLYCHLORINATED BIPHENYLS MSDS Date:10/01/1988 FSC:5910 NIIN:01-019-8871 Status Code:A MSDS Number: CJDKH === Responsible Party === Company Name: MONSANTO CO Address:800 N LINDBERGH BLVD **Box:UNKNOW** City:ST LOUIS State:MO ZIP:63167 Country:US Info Phone Num:314-694-1000 **Emergency Phone Num:314** -694-1000 Preparer's Name: PAUL R MICHAEL, SAFETY CAGE:3Y784 === Contractor Identification === Company Name: GENERAL ELECTRIC CO CAPACITOR PRODUCTS DEPARTMENT Address: JOHN ST Box:City:HUDSON FALLS State:NY ZIP:12839 Country:US Phone:518-746-5750 CAGE:01002 Company Name: MONSANTO CO, FIBERS BUSINESS UNIT Address:800 N LINDBERGH BLVD Box:City:SAINT LOUIS State:MO ZIP:63167 Country:US Phone:314-694-1000 CAGE:3Y784

Ingred Name:POLYC

HLORINATED BIPHENYLS (PCBS) (SARA III) CAS:1336-36-3 RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Reports of Carcinogenicity:NTP:YES IARC:YES OSHA:NO Health Hazards Acute and Chronic:EYES: MODERATELY IRRITATING TO EYE TISSUES. SKIN: CAN BE ABSORBED THROUGH INTACT SKIN. MAY CAUSE DEFATTING. A POTENTIAL FOR CONTACTING CHLORACNE. INHALATION: POSSIBLE LIVER INJURY. INGESTION: SLIGH TLY TOXIC. Explanati

on of Carcinogenicity:IARC: PROBABLE CARCINOGENIC. NTP: REASONABLY ANTICIPATED TO BE CARCINOGENIC.

Effects of Overexposure:CAN CAUSE DERMATOLOGICAL SYMPTOMS; HOWEVER, THESE ARE REVERSIBLE UPON REMOVAL OF EXPOSURE SOURCE.

First Aid:EYES: IRRIGATE IMMEDIATELY WITH COPIOUS QUANTITIES OF RUNNING WATER FOR AT LEAST 15 MIN IF LIQUID OR SOLID PCBS GET INTO THEM. SKIN:CONTAMINATED CLOTHING SHOULD BE REMOVED AND THE SKIN WASHED

THOROUG HLY WITH SOAP AND WATER. HOT PCBS MAY CAUSE THERMAL BURNS. INHALATION: REMOVE TO FRESH AIR. IF SKIN RASH OR RESPIRATORY IRRITATION PERSISTS, CONSULT A PHYSICIAN. (IF ELECTRICAL EQUIPMENT ARCS OVER, P CBS MAY DECOMPOSE TO PRODUCE HYDROCHLORIC ACID). INGESTION: CONSULT A PHYSICIAN. DO NOT INDUCE VOMITING OR GIVE ANY OILY LAXATIVES. (IF LARGE AMOUNTS ARE INGESTED, GASTRIC LAVAGE IS SUGGESTED).

Flash Point:>141.C, 285.8F

Extinguishing Media:PCBS ARE FIRE-RESISTANT COMPOUNDS. Fire Fighting Procedures:STANDARD FIRE FIGHTING WEARING APPAREL AND SELF-CONTAINED BREATHING APPARATUS SHOULD BE WORN WHEN FIGHTING FIRES THAT INVOLVE POSSIBLE EXPOSURE TO CHEMICAL COMBUSTION PRODUCTS. FIRE FIGHTING EQUIPMEN T SHOULD BE THOROUGHLY CLEANED AND DECONTAMINATED AFTER USE.

Unusual Fire/Explosion Hazard:IF A PCB TRANSFORMER IS INVOLVED IN A FIRE-RELATED INCIDENT, THE O

WNER OF THE TRANSFORMER MAY BE REQUIRED TO REPORT THE INCIDENT. CONSULT AND FOLLOW APPROPRIATE FEDERAL, STATE, AND LOCAL REGULATIONS.

Spill Release Procedures: CLEANUP & DISPOSAL OF LIQUID PCBS ARE STRICTLY REGULATED BY THE FEDERAL GOVERNMENT. VENTILATE AREA. CONTAIN SPILL/LEAK. REMOVE SPILL BY MEANS OF ABSORPTIVE MATERIAL. SPILL CLEANUP PERSONNEL SHOULD USE PROPER PROTECTIVE CLOTHING. ALL WASTES AND R

ESIDUES CONTAINING PCBS SHOULD BE COLLECTED, CONTAINERIZED, MARKED AND DISPOSED OF IN THE MANNER PRESCRIBED BY EPA, & APPLICABLE STATE AND LOCAL LAWS.

Handling and Storage Precautions:CARE SHOULD BE TAKEN TO PREVENT ENTRY INTO THE ENVIRONMENT THROUGH SPILLS, LEAKAGE, USE, VAPORIZATION, OR DISPOSAL OF LIQUID. AVOID PROLONGED BREATHING OF VAPORS OR MISTS. AVOID CONTACT WITH EYES OR P ROLONGED CONTACT WITH SKI N. COMPLY

WITH ALL FEDERAL, STATE, AND LOCAL REGULATIONS.

Other Precautions: FEDERAL REGULATIONS UNDER THE TOXIC SUBSTANCES CONTROL ACT REQUIRE PCBS, PCB ITEMS, STORAGE AREAS, TRANSFORMER VAULTS, AND TRANSPORT VEHICLES TO BE MARDED. SEE 40 CFR 761 FOR DETAILS.

======= Exposure Controls/Personal Protection ==========

- Respiratory Protection:USE NIOSH/MSHA APPROVED EQUIPMENT WHEN AIRBORNE EXPOSURE LIMITS ARE EXCEEDED. FULL FACEPIECE EQUIPMENT IS RECOMMENDED AND,
- IF USED, REPLACES NEED FOR FACE SHIELD AND/OR CHEMICAL SPLASH GOGGLES. THE R ESPIRATOR USE LIMITATIONS SPECIFIED BY NIOSH/MSHA OR THE MANUFACTURER MUST BE OBSERVED.
- Ventilation: PROVIDE NATURAL OR MECHANICAL VENTILATION TO CONTROL EXPOSURE LEVELS BELOW AIRBORNE EXPOSURE LEVELS.
- Protective Gloves:WEAR APPROPRIATE CHEMICAL RESISTANT GLOVES TO PREVENT SKIN CONTACT.
- Eye Protection:WEAR CHEMICAL SPLASH GOGGLES AND HAVE EYE BATHS AVAILABLE.

Other Protective Equipment:WEAR APPROPRIA

TE PROTECTIVE CLOTHING. PROVIDE A SAFETY SHOWER AT ANY LOCATION WHERE SKIN CONTACT CAN OCCUR. Work Hygienic Practices: WASH THOROUGHLY AFTER HANDLING. Supplemental Safety and Health NONE HCC:Z3 Vapor Pres:(MM HG @100F).005-.00006 Viscosity:(CENTISTOKES)3.6-540 Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid: PCBS ARE VERY STABL E, FIRE-RESISTANT COMPOUNDS. Hazardous Decomposition Products: CARBON MONOXIDE, CARBON DIOXIDE, HYDROGEN CHLORIDE, PHENOLICS, ALDEHYDES AND OTHER TOXIC COMBUSTION PRODUCTS. Waste Disposal Methods: CONSULT THE APPLICABLE STATE AND LOCAL REGULATIONS PRIOR TO ANY DISPOSAL OF PCBS OR PCB-CONTAMINATED ITEMS. CONSULT WITH 40 CFR PART 761 FOR FEDERAL REQUIREMENTS. Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and

assume responsibility for the suitability of this information to their

particular situation.