

CIBA-GEIGY CORP REN PLASTICS DIV -- ADHESIVE RESIN C-7 -- 8040-01-435-4081

=====
Product Identification
=====

Product ID:ADHESIVE RESIN C-7
MSDS Date:06/25/1995
FSC:8040
NIIN:01-435-4081
Status Code:A
MSDS Number: CKFBK
=== Responsible Party ===
Company Name:CIBA-GEIGY CORP REN PLASTICS DIV
Address:4917 DAWN AVE
City:EAST LANSING
State:MI
ZIP:48823-5605
Country:US
Info Phone Num:517-351-5900
Emer
gency Phone Num:1-800-888-8372
Preparer's Name:M. MUNSELL
CAGE:02684
=== Contractor Identification ===
Company Name:CIBA SPECIALTY CHEMICALS CORPORATION
Address:4917 DAWN AVE
Box:City:EAST LANSING
State:MI
ZIP:48823-5691
Country:US
Phone:517-351-5900
CAGE:02684

=====
Composition/Information on Ingredients
=====

Ingred Name:BENTONITE
CAS:1302-78-9
RTECS #:CT9450000
Other REC Limits:*=AIR (TOTAL DUST)
OSHA PEL:15MG/M3
ACGIH TLV:10MG/M3*

Ingred Name:CALCIUM CARBONATE
CAS:1317-6

5-3

Other REC Limits:*=AIR (TOTAL DUST)

OSHA PEL:15 MG/M3

ACGIH TLV:10 MG/M3*

Ingred Name:DIGLYCIDYL ETHER OF BISPHENOL A. EPOXY RESIN

CAS:25068-38-6

RTECS #:CE6880000

=====
===== Hazards Identification =====

Health Hazards Acute and Chronic:(HEATED PRODUCT MAY PRODUCE INHALABLE VAPORS.) HEALTH HAZARDS: SKIN IRRITATION: IRRITANT. EYE IRRITATION: IRRITANT. SENSITIZATION: POSSIBLE IN SUSCEPTIBLE INDIVIDUALS.

Effects of Overexposure:SKIN AND EYE IRRITATION AND ALLERGIC SKIN AND RESPIRATORY REACTIONS.

Medical Cond Aggravated by Exposure:SKIN AND EYE CONDITIONS.

=====
===== First Aid Measures =====

First Aid:EYES: IMMEDIATELY FLLUSH EYES WITH WATER FOR AT LEAST 15 MINUTES. CALL A PHYSICIAN. SKIN: WASH WITH SOAP AND WATER. REMOVE CONTAMINATED CLOTHING AND LAUNDER BEFORE RE-USE. INGESTION: IF CONS CIOUS, GIVE PLENTY OF WATER TO DRINK. DO NOT INDUCE VOMITING. CALL A PHYSICIAN. IN

HALATION: REMOVE TO FRESH

AIR. GIVE OXYGEN AND/OR ARTIFICIAL RESPIRATION, IF NEEDED. CALL A PHYSICIAN. OTHER : REFERRAL TO A PHYSICIAN IS RECOMMENDED IF THERE IS ANY QUESTION ABOUT THE SERIOUSNESS FO ANY INJURY.

=====
===== Fire Fighting Measures =====

Flash Point Method:PMCC

Flash Point:=136.7C, 278.F

278F

Extinguishing Media:CO2, DRY CHEMICAL, FOAM.

Fire Fighting Procedures:USE SELF-CONTAINED BREATHING APPARATUS.

Unusual Fire/Explosion Hazard:DEC

COMPOSITION AND COMBUSTION PRODUCTS MAY
BE TOXIC.

===== Accidental Release Measures =====

Spill Release Procedures:REMOVE SPILLAGE BY ABSORBING IN ABSORBENT
MATERIAL.

===== Handling and Storage =====

Handling and Storage Precautions:WARNING! COMBUSTIBLE. CAUSES SKIN AND
EYE IRRITATION. MAY CAUSE ALLERGIC SKIN AND RESPIRATORY REACTION.
KEEP AWAY FROM HEAT AND FLAME. AVOID CONTACT WITH EYES, SKIN, AND
CLOTHING

. AVOID BREATHING VAPOR OR MIST. AVOID PROLONGED OR
REPEATED CONTACT WITH SKIN.

Other Precautions:KEEP CONTAINER CLOSED. USE WITH ADEQUATE
VENTILATIONS. WASH THOROUGHLY AFTER HANDLING.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH APPROVED ORGANIC VAPOR CARTRIDGE
RESPIRATOR WHEN VAPOR/MIST EXPOSURE IS LIKELY.

Ventilation:GENERAL MECHANICAL AND LOCAL EXHAUST IN ACCORDANCE WITH
ACGIH RECOMMENDATIONS.

Protective Gloves:WEAR
R IMPERMEABLE GLOVES.

Eye Protection:WEAR SPLASH-PROOF CHEMICAL GOGGLES.

Supplemental Safety and Health

===== Physical/Chemical Properties =====

Vapor Pres: