## NSN 1560-01-068-2052

Upper Longer Repair Installation - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/1560-01-068-2052

**End Application:** 

Aircraft model no. T-38

## **General Description:**

Consists of fasteners, 1 p/n hl19pb5-5, 2 p/n hl20pb5-7, 7 p/n hl20pb6-6, 9 p/n hl20pb6-7, 1 p/n hl20pb6-8, 3 p/n hl86tw5, 17 p/n hl86tw6, 2 p/n nas1670-3l5, 4 p/n nas1670-3l6, 2 p/n nas1670-3l7, 2 p/n nas1670-3l8, 2 p/n nas1670-3l9, 2 p/n nas1670-4l9, 1 ms20426ad5-8, 1 p/n hl70tw-5, and the following items to be made from stock listed matl, 1 ea p/n 7839323-02 plate, p/n 7839324-01 shim, p/n 7839311-01 fitting, p/n 7839335-01 shim, p/n 7839342-01 shim

Shelf Life:

N/a

**Unit Of Measure:** 

--

**Demilitarization:** 

Yes - demil/mli