## NSN 1560-01-208-9939

Pylon Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/1560-01-208-9939

			_
Fnd	Δn	nlica	ition:
LIIU	$\neg$ P		4110111

F-5e/f aircraft

## **General Description:**

W.S. 93.5 forward shear pin counterbore; c/o: t301s1-11 piloted spotface (1), 10w064-310c105 washer(1), 14-028101 repair dwg(1 copy), 14-028101-7 bushing(1), cutter, spotfacer, back(1), drill, twist, straight shank(1), metric chucking reamer, straight shank(1)

Shelf Life:

N/a

**Unit Of Measure:** 

--

Demilitarization:

Yes - demil/mli