NSN 1560-01-592-9335

Aircraft Structural Component Support - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/1560-01-592-9335

Overall Length:
3.300 inches
Overall Width:
1.500 inches
Material Thickness:
0.250 inches
Product Name:
Repair doubler horizontal stabilizer
Aircraft Location:
Horizontal stabilizer torque box
Aircraft Mission Design Series:
F-15a/b
Special Features:
Heat treat t851
Material:
Aluminum alloy 2024
Material Specification:
Mms 1406 condition t851 mfr ref single material response
Shelf Life:
N/a
Unit Of Measure:
Demilitarization:
Yes - demil/mli
Fiig:
A11800