

View Online at <https://aerobasegroup.com/nsn/2520-00-038-4525>

Unable To Decode:

Unable to decode and unable to decode

Unable To Decode:

Unable to decode and unable to decode

Overall Length:

2.250 inches

Flange Thickness:

0.2800 inches

Unable To Decode:

Unable to decode and unable to decode

Unable To Decode:

Unable to decode and unable to decode

Hub Length:

1.180 inches

Unable To Decode:

Unable to decode and unable to decode

Bore Style (non-core):

Err-090

Shaft Facility Spline Quantity:

10

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fiig:

A521s0