

View Online at <https://aerobasegroup.com/nsn/2520-00-319-0296>

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Overall Length:**

3.6875 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Flange Thickness:**

0.3750 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Bore Length:**

3.000 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Hub Length:**

2.500 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Bore Style (non-core):**

Err-090

**Shaft Facility Spline Quantity:**

10

**Fsc Application Data:**

Transfer case, truck chassis

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fig:**

A521s0