

View Online at <https://aerobasegroup.com/nsn/2520-00-618-4285>

Unable To Decode:

Unable to decode and unable to decode

Unable To Decode:

Unable to decode and unable to decode

Overall Length:

2.875 inches

Unable To Decode:

Unable to decode and unable to decode

Flange Thickness:

0.3125 inches

Unable To Decode:

Unable to decode and unable to decode

Unable To Decode:

Unable to decode and unable to decode

Bore Length:

2.000 inches

Unable To Decode:

Unable to decode and unable to decode

Hub Length:

2.562 inches

Unable To Decode:

Unable to decode and unable to decode

Bore Style (non-core):

Err-090

Shaft Facility Spline Quantity:

6

Fsc Application Data:

Universal joint, propeller shaft, combat vehicle

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fig:

A521s0