

View Online at <https://aerobasegroup.com/nsn/2520-00-734-9096>

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Overall Length:**

3.5625 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Flange Thickness:**

0.3750 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Unable To Decode:**

Unable to decode and unable to decode

**Bore Length:**

2.5625 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Hub Length:**

2.125 inches

**Unable To Decode:**

Unable to decode and unable to decode

**Bore Style (non-core):**

Err-090

**Shaft Facility Spline Quantity:**

10

**Fsc Application Data:**

Shaft, propeller, vehicular

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No

**Fiig:**

A521s0