

View Online at <https://aerobasegroup.com/nsn/2520-00-736-0236>

Test Data Document:

19207-10900521 drawing (this is the basic governing drawing, such as a contractor drawing, original equipment manufacturer drawing, etc.; excludes any specification, standard or other document that may be referenced in a basic governing drawing)

General Description:

Qoperating pressure range 0 to 250psi; opening pressure range 95 plus or minus 10 psi; closing pressure setting 115 plus or minus 10 psi; proof pressure 1000 psi; burst pressure 7500 psi; forfurther information see drawing

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No