

View Online at <https://aerobasegroup.com/nsn/2840-01-577-1186>

Furnished Items:

Tube, oil supply 1, tube, oil inlet 1, nut, self-locking 1

Supply Items And Quantities:

5340-01-408-4034 clamp, loop 2, 3120-01-408-7542 bushing, split half 4, 5340-01-144-3957 bracket 1, 5306-00-523-2857 bolt, machine 1, 5306-00-308-3519 bolt, machine 1

Product Name:

Ecp g404-l-23 depot retrofit kit exhaust frame c-sump supply tube cracking

Functional Description:

This kit proposes is to fix the exhaust frame c-sump supply tube cracking problem on the f404-ge-400/ f404-ge-402 turbofan engine.

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fiig:

A23800