

View Online at <https://aerobasegroup.com/nsn/2840-01-577-1206>

Furnished Items:

9352m42p05 clamp loop 2 ea, 9352m41p03 bushing split half 4 ea, 4072t75g03 bracket, j643p05a bolt 1ea, j644p13a bolt 1ea, j490p03b nut, self-locking 1ea.

Product Name:

Ecp g404-l-23 i-level retrofit kit exhaust frame c-sump supply tube cracking

Functional Description:

This kit proposes is to fix the exhaust frame c-sump supply tube cracking problem on the f404-ge-400/ f404-ge-402 turbofan engine.

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

Yes - demil/mli

Fiig:

A23800