Impeller And Shaft Assembly - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4140-00-433-9571

End Application:

Fuller co. Rotary positive blower, model m514-88

Criticality Code Justification:

Text

Extra Long Reference Number:

908-66-3-0964-05and908-66-3-0965-05

General Description:

Figure eight positive displacement impellers mtd on shafts; machined and toleranced for intermeshing rotation as matched set; consist of 1

ea part no. 908-66-3-0964-05 long drive shaft assembly and 1 ea part no 908-66-0965-05 short intermeshing shaft assembly

Reference Number Differentiating Characteristics:

As differentiated by extra long reference number

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No