NSN 4920-01-347-1719

Aircraft Engine Maintenance Fixture - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4920-01-347-1719

| End Application: |
|--|
| F100-pw-200/220 turbo fan engine age. |
| Nominallength: |
| 3.000 inches |
| Nominalwidth: |
| 3.000 inches |
| Nominalheight: |
| 1.000 inches |
| Special Features: |
| Form block is contoured to fit the repair area and centers with plug in the 0.470 - 0.480 dia. Hole. Entire tool will attach to flap with a toggle |
| clamp; aluminum |
| Functional Description: |
| Used to attach to the external augmentor flap to repair the linkage screw hole wear |
| Reference Data And Literature: |
| Serd no. 6479; t.O. 2j-f100-94 |
| Shelf Life: |
| N/a |
| Unit Of Measure: |
| - |
| Demilitarization: |
| No |
| Fiig: |
| A505c0 |
| |