NSN 4920-01-388-7621

Dead Load Test Adapter - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4920-01-388-7621

| | | | _ |
|------|----------|-------|---------|
| Fnd | Δn | nlica | ition: |
| LIIU | \neg P | | 4110111 |

F117-pw-100

Functional Description:

Required to attach a sling to a dead load test table during integrity inspection of the sling

Reference Data And Literature:

Pw serd no.1727

General Description:

Adapter, dead load, 17.5in I, 10.0in w, 1.7in h

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No