## NSN 4920-01-388-7677

No

Dead Load Test Adapter - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/4920-01-388-7677

End Application:
F117-pw-100
Special Features:
Adapter, lifting, high pressure turbine first turbine disk
Functional Description:
Required to dead load test the lifting adapter used to lift the first stage high pressure turbine disk
Reference Data And Literature:
Pw serd no.1759
General Description:
Adapter, dead load test, 11.3in dia, 1.5in h
Shelf Life:
N/a
Unit Of Measure:
Demilitarization: