

View Online at <https://aerobasegroup.com/nsn/4920-01-470-4895>

**Special Features:**

Include sensor excitation of 5, 10, 12 or 24 vdc; factory default setup is 0-100 mvdc input with 10 vdc sensor excitation and scaled to display 0-100.0

**General Description:**

Strain gage meter that accepts 0-100 mv, +50 mv, 0-5 v, 1-5 v, 0-10, v, 4-20 ma or 4-20 madc signal inputs

**Shelf Life:**

N/a

**Unit Of Measure:**

--

**Demilitarization:**

No