NSN 5133-01-393-4822

Hand Counterbore - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/5133-01-393-4822

| | _ | | | |
|------|----------|------|--------|------|
| End | Λn | nlic | · atic | ۱n: |
| LIIU | Δ | DIIL | ,auc | ,,,, |

Engine assembly tf117 pw100

Supplementary Features:

To repair the turbine exhaust case struts it may be necessary to remove the kiel tubes; to be removed from the assembly the head of the tube must be machined from it; pwa81333 piloted counterbore consists of a colbalt drill modified to controlled dimensions

| Ch | _lf | Life: | |
|-----|-----|-------|--|
| OII | EII | LIIE. | |

N/a

Unit Of Measure:

__

Demilitarization:

No

Fiig:

A188a0