## NSN 5210-01-515-7123

External Indicating Gage - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/5210-01-515-7123

## **Special Features:**

Required for repair of worn thirdstage turbine disk-refp/n 4080603, gageused during preliminary machining that prepares disk repair srfce, grit blastand plasma coating, instlld in pwa72643 fixture on a vtl or equivalent, presetdial indicator of gage to zero prior to each use, using pwa72645 set master, serd number 9418

$\sim$			•
Sh	Δlt	1 1	to.
<b>UII</b>	CII.	_	ıc.

N/a

**Unit Of Measure:** 

Demilitarization:

Yes - demil/mli

Fiig:

T299-g