## NSN 5999-01-098-4945

Flame Failure - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/5999-01-098-4945

	-			
End	Λn	nlic	· atic	۱n:
LIIU	$\Delta$	DIIL	,auc	,,,,

Part for fire-eye multi-burner safeguard system mb-2 num 5 blanking andannealing gas furnace

**General Description:** 

Uv amplifier flame failure response time less than 4 seconds

Shelf Life:

N/a

**Unit Of Measure:** 

\_\_

Demilitarization:

No