Motor Starter - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/6110-01-409-1378

| Speed A   | Adjustments:                                             |
|-----------|----------------------------------------------------------|
| 0 to full | speed                                                    |
| Ac Volt   | age Rating:                                              |
| 440.0 vo  | blts                                                     |
| Freque    | ncy Rating:                                              |
| 60.0 he   | tz                                                       |
| Actuati   | on Method:                                               |
| Magneti   | c                                                        |
| Perforn   | nance Type:                                              |
| Automa    | tic                                                      |
| Size De   | signator:                                                |
| 1         |                                                          |
| Duty Cy   | /cle:                                                    |
| Continu   | DUS                                                      |
| Operati   | ng Voltage Characteristic:                               |
| Full      |                                                          |
| Horsep    | ower Rating:                                             |
| 200.000   |                                                          |
| Actuato   | or Voltage:                                              |
| 440.0 a   | >                                                        |
| Load P    | rotection Type:                                          |
| Overloa   | d                                                        |
| Ambier    | t Temp:                                                  |
| 50.0 de   | grees celsius                                            |
| Nationa   | I Electrical Manufacturers Association Standards Design: |
| Designe   | ed per nema std                                          |
| Control   | Туре:                                                    |
| Local     |                                                          |
| Phase:    |                                                          |
| Three     |                                                          |
| Shelf Li  | fe:                                                      |
| N/a       |                                                          |
| Unit Of   | Measure:                                                 |
|           |                                                          |
|           | arization:                                               |
| No        |                                                          |
| Fiig:     |                                                          |