

View Online at <https://aerobasegroup.com/nsn/6610-00-007-1030>

Scale Quantity:

1

Scale Name:

G unit

Pointer Quantity:

1 and 2

Pointer Finish:

Fluorescent

Scale Marking And Surface Finish:

Numerals fluorescent err-100

Knob Quantity:

1

Knob Purpose:

Used to zero pointers

Pointer Purpose:

Instantaneous acceleration and maximum negative acceleration

Pointer Type:

Main and record

Scale Range:

Minus 2 to plus 4 gravity units

Scale Smallest Increment Graduation:

0.2 of 1 g unit

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

Yes - demil/mli

Fig:

T261-a