Mechanical Accelerometer - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/6610-00-845-7530

Scale Quantity:
1
Scale Name:
G unit
Pointer Quantity:
1 and 1 and 1
Pointer Finish:
Nonluminous and nonluminous and nonluminous
Scale Marking And Surface Finish:
Numerals nonluminous err-100
Knob Quantity:
1
Knob Purpose:
Used to set pointers
Pointer Purpose:
Instantaneous acceleration; minus g acceleration; plus g acceleration
Pointer Type:
Acceleration and minus and plus
Mounting Method:
Bezel
Scale Range:
Minus 5.0 g to plus 10.0 g
Scale Smallest Increment Graduation:
0.5 g
Shelf Life:
N/a
Unit Of Measure:
-
Demilitarization:
Yes - demil/mli
Fiig:
T261-a