

View Online at <https://aerobasegroup.com/nsn/6660-01-292-8986>

General Description:

Testtemperature circuits; remove the temperature probe from the motor aspirater radiation shield; connect the model1452 temperature calibrator to thejack in the radiation shield; using theprecision resistor tables test the temperature circuits iaw qualimetrics tech manual; communication between sensorstower and wau model 17b is required for this tes (see serd 0045)

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No