

View Online at <https://aerobasegroup.com/nsn/6680-01-195-3245>

End Application:

Air dry corporation of america, dewpoint indicator assembly

General Description:

Dew point, -70 degrees f to -20 degrees f; color change, green to blue

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No