

View Online at <https://aerobasegroup.com/nsn/6760-01-039-0127>

Carrying Case:

Provided

Accessory Components And Quantity:

Mallory px13 battery 1

Usage Design:

Motion picture camera or still picture camera

Measurement Unit:

Asa exposure index and exposure value and f-stop and seconds

Scale Measurement Range:

+0.0005/+0.2500

Graduation Interval:

Various multiple

Sensitivity Range:

+0.065/+32000.000 footcandle

Shelf Life:

N/a

Unit Of Measure:

--

Demilitarization:

No

Fiig:

T134-c