NSN 8040-01-562-4183

Adhesive Patch Repair Kit - Page 1 of 1



View Online at https://aerobasegroup.com/nsn/8040-01-562-4183

Р	ro	d	u	ct	N	an	ne:

Af 300 series cargo liner repair

Special Features:

For repair of damage to airline baggage compartment liners. Self contained kit contains in sealed bag; instruction sheet, tape for mounting kit on liner, 2 spreaders, pair of vinyl gloves, epoxy kit, reinforcement scrim, razor blade, sand paper, cleaning cloth, 8 x 8 inch patch. For repair of I or u shaped tears on liners of 0.01 inch thick liners or greater

Ch	~If	I it	·~•

N/a

Unit Of Measure:

--

Demilitarization:

No

Fiig:

A23800