

GARDINER SOLDER CO. -- 1135 SOLDERING FLUID -- 3439-00-009-8808

===== Product Identification =====

Product ID:1135 SOLDERING FLUID

MSDS Date:01/01/1985

FSC:3439

NIIN:00-009-8808

MSDS Number: BCVGS

=== Responsible Party ===

Company Name:GARDINER SOLDER CO.

Address:4820 S CAMPBELL AVE

City:CHICAGO

State:IL

ZIP:60632-1494

Country:US

CAGE:84311

=== Contractor Identification ===

Company Name:GARDINER

SOLDER COMPANY DIV GARDINER METAL CO

Address:4820 S CAMPBELL AVE

Box:City:CHICAGO

State:IL

ZIP:60632-1494

Country:US

Phone:312-847-0100 CHEMTREC AFTER HOURS

CAGE:84311

===== Composition/Information on Ingredients =====

Ingred Name:ISOPROPYL ALCOHOL (SARA III)

CAS:67-63-0

RTECS #:NT8050000

Fraction by Wt: 65%.

OSHA PEL:400 PPM/500 STEL

ACGIH TLV:400 PPM/500STEL;9192

Ingred Name:ROSIN

Fraction by Wt: 35%.

===== Hazards Identification =====

ity in Water:APPRECIABLE
Appearance and Odor:AMBER-ETHEREAL.
Percent Volatiles by Volume:82.

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES
CAN REACT VIGOROUSLY WITH OXIDIZING MATERIAL
Hazardous Decomposition Products:NONE

===== Disposal Considerations =====

Waste Disposal Methods:INCINERATE OR PLACE ABSORBENT INTO RUBBISH CART.
(MFG RECOMMENDATION).

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.