

FURANE PRODUCTS, A DIV OF CIBA GEIGY CORP -- EPOCAST 41-A. PART-A -- 8040-00-142-9048

=====
Product Identification
=====

Product ID:EPOCAST 41-A. PART-A

MSDS Date:07/11/1988

FSC:8040

NIIN:00-142-9048

Kit Part:Y

MSDS Number: BDBRS

=== Responsible Party ===

Company Name:FURANE PRODUCTS, A DIV OF CIBA GEIGY CORP

Address:5121 SAN FERNADO ROAD W.

City:LOS ANGELES

State:CA

ZIP:90039-1011

Emergency Phon

e Num:818-247-6210

CAGE:GO767

=== Contractor Identification ===

Company Name:CHEMICAL COMMODITIES AGENCY, INC.

Address:27447 PACIFIC STREET

Box:City:HIGHLAND

State:CA

ZIP:92346-2640

Country:US

Phone:909-864-2310

CAGE:60777

Company Name:CIBA SPECIALTY CHEMICALS CORP, N. A. / PERFORMANCE

POLYMERS

Address:5121 SAN FERNANDO RD WEST

Box:City:LOS ANGELES

State:CA

ZIP:90039-1011

Country:US

Phone:818-247-6210/800-873-1138

CAGE:99384

Company Name:FURANE PRODUCTS, M & T CHEMICALS, INC.

CAGE:GO767

===

=====
Composition/Information on Ingredients
=====

Ingred Name:EPOXY RESINS
Fraction by Wt: 100%

=====
Hazards Identification
=====

Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO
Health Hazards Acute and Chronic:MAY CAUSE SOME IRRITATION.PROLONGED OR
REPEATED EXPOSURE CAN CAUSE ALLERGIC REACTION.
Effects of Overexposure:SLIGHTLY IRRITATION.
Medical Cond Aggravated by Exposure:ALLERGIC DERMATITIS OR RESPIRATORY
RESPONSE IN SUSCEPTI
BLE INDIVIDUALS MAY BE DELAYED.IT MAY APPEAR
AFTER WEEKS OR EVEN MONTHS OF FREQUENT & PROLONGED CONTACT.

=====
First Aid Measures
=====

First Aid:INHALE:REMOVE TO FRESH AIR, GIVE CPR/O*2 IF
NEED;EYES/SKIN:FLUSH W LG AMTS H*2O FOR 15 MIN;INGEST:RINSE MOUTH;
GER MEDICAL ATTENTION FOR EYES, INGEST, OR SYMPTOMS OF
OVEREXPOSURE.

=====
Fire Fighting Measures
=====

Flash Point Method:PMCC
Flash Point:>245F/118.5
C
Extinguishing Media:WATER,FOAM,OR DRY CHEMICAL POWDER
Fire Fighting Procedures:WEAR SELF-CNTND BRTHG APP:H*2O SPRAY TO COOL
CONTR.
Unusual Fire/Explosion Hazard:MATL MAY/MAY NOT BURN. CONTAINER MAY
EXPLODE IN HEAT OF FIRE.FIRE MAY YIELD TOXIC GASES.

=====
Accidental Release Measures
=====

Spill Release Procedures:EVACUATE UNPROTECTED PERSONS. ELIM IGNITION
SOURCES. STOP LEAK. H*2O SPRAY COOL CONT/DIVERT SPILL FROM
FIRE/HEAT. PROVIDE VENTILATION. AB
SORB W/COMMERCIAL
ABSORBENT,SHOVEL INTO METAL DRUMS:LG SPILL:DI KE W COMMERCIAL
ABSORBENT,PUMP INTO COVERED DRUMS.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORE IN COOL,DRY,WELL VENT,LOW FIRE
RISK AREA. PROTECT FROM PHYSICAL DAMAGE.AVOID ANY PHYSICAL CONTACT.
KEEP CONTAINERS TIGHTLY CLOSED.
Other Precautions:MAINTAIN STTRICT HYGIENE, AVOID PHYSICAL CONTACT,
REMOVE & WASH CONTAMINATED CLOTHING. MFG SUGGESTS USE OF

PROTECTIVE

SKIN CREAMS. EXHAUST CURING OVENS TO OPEN AIR. AVOID TEMPERATURE EXTREMES.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE USUALLY.

Ventilation:ADEQUATE GENERAL VENTILATION.

Protective Gloves:PV/RUBBER

Eye Protection:SAFETY/CHEM GOGGLES

Other Protective Equipment:FULL WORK CLOTHING TO PREVENT REPEATED OR PROLONGED CONTACT.

Supplemental Safety and Health
PART A OF A TWO PART KIT.

===== Physical/Chemical Properties =====

HCC:N1

Boiling Pt:B.P. Text:DECOMPOSES

Vapor Pres:1

Spec Gravity:1.16

Evaporation Rate & Reference: