

SPRAGUE ELEC. CO. -- 200P1903 -- 5910-00-172-5283

=====
Product Identification
=====

Product ID:200P1903

MSDS Date:01/01/1985

FSC:5910

NIIN:00-172-5283

MSDS Number: BDFKJ

=== Responsible Party ===

Company Name:SPRAGUE ELEC. CO.

Address:61 SPIT BROOK RD SUITE 305

City:NASHUA

State:NH

ZIP:03060

Country:US

Emergency Phone Num:603-883-5544

CAGE:56289

=== Contractor Identification ===

Company Name:SPR

AGUE ELECTRIC CO WORLD HEADQUARTERS

Address:61 SPIT BROOK RD SUITE 305

Box:City:NASHUA

State:NH

ZIP:03060

Country:US

Phone:603-883-5544/FAX 603-880-1910

CAGE:56289

=====
Composition/Information on Ingredients
=====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000

EPA Rpt Qty:1 LB

DOT Rpt Qty:1 LB

=====
Hazards Identification
=====

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES

C

ANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

=====
First Aid Measures
=====

First Aid:EYES:FLUSH W/WATER IMMED.SKIN:WASH W/SOAP IMMED.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR. AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNCONSCIOUS PE RSON VOMIT.

=====
Accidental Release Measures
=====

Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNO FF.ISOLATE & NOTIFY PROPER AUTHORITIES.

=====
Handling and Storage
=====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENT.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
Ventilation:LOCAL EXHAUST
Protective Gloves:RUBBER-IMPERV
Eye Protection:GOGGLES,FACE SHIELD
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT
Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS.CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.

=====
Physical/Chemical Properties
=====

HCC:Z3
Appearance and Odor:LIGHT STRAW COLORED-LIQUID,AROMATIC ODOR.

=====
Stability and Reactivity Data
=====

STRONG OXIDIZERS

=====
Disposal Considerations
=====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINERATION.ONLY APPR

OVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.