

EXXON CO, USA -- 1208 TURBINE LUBRICANT -- 9150-00-235-9061

===== Product Identification =====

Product ID:1208 TURBINE LUBRICANT

MSDS Date:01/01/1985

FSC:9150

NIIN:00-235-9061

MSDS Number: BDLQQ

=== Responsible Party ===

Company Name:EXXON CO, USA

Emergency Phone Num:713-656-3424

CAGE:GO864

=== Contractor Identification ===

Company Name:EXXON CO, USA

Box:2180

CAGE:GO864

Company Name:EXXON COMPANY

U.S.A.

Address:Box:2180

City:HOUSTON

State:TX

ZIP:77252-2180

Country:US

Phone:713-656-5949 / 713-656-3424

CAGE:29700

Company Name:SOUTH COAST TERMINALS, INC

Address:7401 WALLISVILLE ROAD

Box:15535

City:HOUSTON

State:TX

ZIP:77020

Country:US

Phone:713-672-2401/800-424-9300(CHEMTREC)

CAGE:1L506

===== Composition/Information on Ingredients =====

Ingred Name:PETROLEUM HYDROCARBONS

===== Hazards Identification =====

Effects of Overexposure:PROLO

INGED OR REPEATED SKIN CONTACT MAY COUSE
MILD SKIN IRRITATION.

=====
First Aid Measures
=====

First Aid:SKIN:WASH WELL W/SOAP & WARM WATER.EYES:(SPLASH)FLUSH W/CLEAR
WATER FOR 15 MIN OR UNTIL IRRITATION SUBSIDES.

=====
Fire Fighting Measures
=====

Flash Point:480F COC

Lower Limits:1.0

Upper Limits:6.0

Extinguishing Media:FOAM, DRY CHEMICAL, CO*2, OR WATER FOG OR SPRAY

Fire Fighting Procedures:USE AIR-SUPPLIED BREA

THING EQUIP, COOL CANS

W/WATER SPRAY.

Unusual Fire/Explosion Hazard:AVOID BREATHING VAPOR OR FUMES. DO NOT MI
OR STORE W/STRONG OXIDANTS LIKE LIQ CHLORINE, CONC OXYGN.

=====
Accidental Release Measures
=====

Spill Release Procedures:RECOVER FREE LIQUID. ADD ABSORBENT (SAND,
EARTH, ETC) TO SPILL AREA. KEEP PETROLEUM PRODUCTS OUT OF SEWERS &
WATERCOURSES BY DIKING OR IMPOUNDNG. ADVISE AUTHORITIES IF PRODUCT
HAS ENTERED SEWERS, WATE RCOURSES OR EXTE
NSIVE LAND AREAS.

=====
Handling and Storage
=====

Handling and Storage Precautions:KEEP CONTAINERS CLOSED WHEN NOT IN
USE.DO NOT HANDLE OR STORE NEAR HEAT,SPARKS,FLAME OR STRONG
OXIDANTS.

Other Precautions:AVOID BREATHING OIL MIST.REMOVE OIL-SOAKED CLOTHING &
CLEAN BEFORE REUSE.DISCARD OIL-SOAKED SHOES.WASH SKIN WELL W/SOAP &
WATER AFTER HANDLING.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:USE

SUPPLIED AIR RESP.PROTECTION.IN CONFINED OR
ENCL AREAS.

Ventilation:LOCAL CAPTURE FUMES & VAPORS.CONFINED:>60FPM HOOD

Protective Gloves:CHEM RESISTANT

Eye Protection:SPLASH GOGGLES/SHIELD

Other Protective Equipment:CHEM RESIST APRON,SKIN PROTECTION.

Supplemental Safety and Health

VAPOR PRESSURE: