View NSN Online: https://aerobasegroup.com/nsn/9150-00-261-7895 WITCO(GOLDEN BEAR DIVISION) -- MIL-F-12070, FOG OIL -- 9150-00-261-7895 Product ID:MIL-F-12070,FOG OIL MSDS Date:01/01/1985 FSC:9150 NIIN:00-261-7895 MSDS Number: BDPNR === Responsible Party === Company Name: WITCO (GOLDEN BEAR DIVISION) Emergency Phone Num:805-393-7110 CAGE:DO968 === Contractor Identification === Company Name: WITCO GOLDEN BEAR DIVISION Address:101 00 SANTA MONICA BLVD SUITE 1470 Box:City:LOS ANGELES State:CA ZIP:90067 Country:US Phone:805-393-7110 CAGE:5H505 Company Name: WITCO (GOLDEN BEAR DIVISION) CAGE:DO968 ======= Composition/Information on Ingredients ======== Ingred Name: PETROLEUM HYDROCARBONS Fraction by Wt: 100% ========== Hazards Identification ================ Effects of Overexposure: DERMATITIS IN VERY SENSITIVE INDIVIDUALS, DIZZINESS, HEADACHE, DROWSINESS, COUGH, DYSPNEA, NAUSEA, COMA ======== First Aid:EYES:FLUSH WITH LARGE QUANTITIES OF WATER-CONTACT PHYSICIAN.SKIN CONTACT:WASH WITH SOAP & WATER.IF SWALLOWED:CONTACT **PHYSICIAN** ============= Fire Fighting Measures ======================== Flash Point:320F COC Extinguishing Media:DRY CHEMICAL,CO\*2,WATERSPRAY Fire Fighting Procedures: STANDARD PETROLEUM PROCEDURES Unusual Fire/Explosion Hazard:NONE ======== Accidental Release Measures =========

Spill Release Procedures:REMOVE WITH ABSORBENT MATERIALSUCH AS SAND,CLAY,ETC;REMOVE FROM WATE BY SKIMMING
========== Handling and Storage ============
Handling and Storage Precautions:STORE IN COOL LOCATION,KEEP CLEAN,0 DRY.WEAR RUBBER GLOVES,FACE SHIELD,COVERALL,ALL-PURPOSE CANISTER MASK.
====== Exposure Controls/Personal Protection =======
Respiratory Protection:NONE Ventilation:NONE Protective Gloves:OIL RESISTANT Eye Protection:SAFET Y GLASSES USEFUL Other Protective Equipment:NONE Supplemental Safety and Health ITEM IS TYPE SGF-2 OF MIL-F-12070
======================================
HCC:V6 Boiling Pt:B.P. Text:N.A. Viscosity:22.9CS Evaporation Rate & DOR Evaporation Rate & DOR
========== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES
======= Disposal Considerations ====================================
Waste Disposal Methods:ABSORPTION OR CONTROLLED BURNING(APPROVED).LOCAL,STATE & FEDERAL REGULATIONS SHOULD BE ABSERVED

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should se

ek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.