

MONSANTO CO -- PHOSPHORIC ACID -- 6810-00-264-6722

=====
Product Identification
=====

Product ID:PHOSPHORIC ACID
MSDS Date:12/12/1988
FSC:6810
NIIN:00-264-6722
MSDS Number: BDQWC
=== Responsible Party ===
Company Name:MONSANTO CO
Address:800 N LINDBERGH BLVD
City:ST LOUIS
State:MO
ZIP:63167
Country:US
Info Phone Num:314-694-2333
Emergency Phone Num:314-694-1000 COLLECT
CAGE:76541
=== Contractor I
dentification ===
Company Name:MONSANTO COMPANY
Address:800 N LINDBERGH BLVD
Box:City:SAINT LOUIS
State:MO
ZIP:63167
Country:US
Phone:314-694-6661 OR 800-332-3111
CAGE:76541

=====
Composition/Information on Ingredients
=====

Ingred Name:PHOSPHORIC ACID (SARA III)
CAS:7664-38-2
RTECS #:TB6300000
Fraction by Wt: 75 - 85%
Other REC Limits:NONE RECOMMENDED
OSHA PEL:1 MG/M3/3 STEL
ACGIH TLV:1 MG/M3/3 STEL; 9293
EPA Rpt Qty:5000 LBS
DOT Rpt Qty:5000 LBS

=====
Haz

ards Identification =====

LD50 LC50 Mixture:LD50 (ORAL, RAT) 3,500-4,400 MG/KG

Routes of Entry: Inhalation:NO Skin:NO Ingestion:YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:CORROSIVE. ACUTE- EYE:MAY CAUSE SEVERE IRRITATION, BURNS, PERMANENT TISSUE DAMAGE. SKIN:MAY CAUSE SEVERE IRRITATION. NO IMMEDIATE BURNING SENSATIONS MAY BE EXPECTED. INHALED:MIST/VAPORS MAY CAUSE SEVE RE RESPIRATORY IRRITATION. ORAL:MAY CAUSE SEVE

RE DIGESTIVE SYSTEM IRRITATION & BURNS, TISSUE DAMAGE.CHRONIC- UNKNOWN.

Effects of Overexposure:CORROSIVE. SEVERE EYES, SKIN, RESPIRATORY AND DIGESTIVE TRACTS IRRITATION AND BURNS

Medical Cond Aggravated by Exposure:NOT KNOWN

===== First Aid Measures =====

First Aid:GET MEDICAL ATTENTION IMMEDIATELY. EYE/SKIN:IMMEDIATELY FLUSH WITH WATER FOR AT LEAST 15 MINUTES. HOLD EYELIDS OPEN.

INHALED:REMOVE TO FRESH AIR & PROVIDE OXYGEN/CPR IF NEEDED.

ORAL:DO

NOT INDUCE VOMI TING. IF CONSCIOUS, DRINK LARGE AMOUNT OF WATER/MILK. CALL A PHYSICIAN IMMEDIATELY. NEVER GIVE ANYTHING BY MOUTH TO AN UNCONSCIOUS PERSON.

===== Fire Fighting Measures =====

Flash Point:NONE

Extinguishing Media:WATER SPRAY, CARBON DIOXIDE, FOAM OR DRY CHEMICAL FOR SURROUNDING FIRE. USE WATER SPRAY TO COOL FIRE EXPOSED CONTAINERS.

Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A FULL FACED SE

LF CONTAINED BREATHING APPARATUS.

Unusual Fire/Explosion Hazard:CAN REACT WITH METALS TO LIBERATE HYDROGEN, A FLAMMABLE GAS.

===== Accidental Release Measures =====

Spill Release Procedures:WEAR FACE PROTECTION, RUBBER BOOTS, APRON AND GLOVES. DIKE SPILL WITH SAND OR CLAY TO KEEP IT OUT OF SEWER SYSTEM. NEUTRALIZE WITH SODA ASH. REQUIRES GOOD VENTILATION AS CO2 IS PRODUCED. PLACE NEUTRAL IZED SPILL IN DOT APPROVED DISPOSAL CONTAINER

Neutralizing

Agent:SODA ASH

=====
Handling and Storage
=====

Handling and Storage Precautions:STORE IN PLASTIC, RUBBER-LINED OR 316 STAINLESS STEEL TANKS DESIGNED FOR H3PO4. STORE DRUMS AWAY FROM HEAT AND OUT OF DIRECT SUNLIGHT.

Other Precautions:KEEP OUT OF REACH OF CHILDREN. DO NOT GET IN EYES, ON SKIN OR ON CLOTHING. AVOID BREATHING MISTS OR VAPORS. WASH THOROUGHLY AFTER HANDLING.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:IF LEVELS EXCEED THE RECOMMENDED HEALTH STANDARDS, WEAR A NIOSH/MSHA APPROVED ORGANIC VAPOR RESPIRATOR FOR ACID. FOR EMERGENCY USE, WEAR A NIOSH APPROVED POSITIVE-PRESSURE MODE, SELF-CONTAINED BREATHING APPARATUS (SCBA).

Ventilation:PROVIDE SUFFICIENT LOCAL EXHAUST VENTILATION TO CONTROL INHALATION EXPOSURES BELOW OSHA'S PEL.

Protective Gloves:NEOPRENE OR RUBBER

Eye Protection:SAFETY GOGGLES & FACE SHIELD

Other Protective Equipment:EYE WASH STATION AND SAFETY SHOWER.

INDUSTRIAL-TYPE WORK CLOTHING AND APRON AS REQUIRED.

Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR FOOTWEAR.

Supplemental Safety and Health

=====
Physical/Chemical Properties
=====

HCC:C1

Boiling Pt:B.P. Text:275F-309F

Melt/Freeze Pt:M.P/F.P Text:0.5F - 70F

Vapor Pres:0.03 @ 68F

Spec Gravity:1.575 - 1.692

pH:< 2

Evaporation Rate & Reference:NOT RELEVANT

Solubil

ity in Water:COMPLETE

Appearance and Odor:CLEAR, COLORLESS, SYRUPY LIQUID - NO ODOR

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

STRONG ALKALIES, METALS, SULFIDES AND SULFITES

Stability Condition to Avoid:EXCESSIVE HEAT

Hazardous Decomposition Products:NONE

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSAL SHOULD BE MADE IN ACCORDANCE WITH ALL
APPLICABLE FEDERAL, STATE AND

LOCAL LAWS AND REGULATIONS.

REPORTABLE QUANTITY (RQ) IS 5000 LBS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.