View NSN Online: https://aerobasegroup.com/nsn/9150-00-265-9405 OCTAGON PROCESS INC. -- VV-C-846A TYPE I; CUTTING FLUID -- 9150-00-265-9405 Product ID:VV-C-846A TYPE I;CUTTING FLUID MSDS Date: 10/02/1987 FSC:9150 NIIN:00-265-9405 MSDS Number: BDRFD === Responsible Party === Company Name: OCTAGON PROCESS INC. Address:596 RIVER ROAD City:EDGEWATER State:NJ ZIP:07020-1105 Country:US Info Phone Num:201-945-9400 Emergency Phone Num: (201)-945-9400 CAGE:82925 === Contractor Identification === Company Name: OCTAGON PROCESS INC. Address:596 RIVER ROAD Box:City:EDGEWATER State:NJ ZIP:07020 Country:US Phone:201-945-9400 CAGE:82925

====== Composition/Information on Ingredients ========

Ingred Name: A-SULFONIC ACID

Ingred Name: MINERAL OIL (EXPOSURE REGULATED AS 'OIL MIST')

CAS:8012-95-1

RTECS #:PY8030000

Other REC Limits:5MG/CUM,OILMIST

OSHA PEL:5 MG/M3

ACGIH TLV:5 MG/M3/10 STEL;9192

====== Hazards

Identification ===========
Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Health Hazards Acute and Chronic:ACUTE:MAY IRRITATE EYES,SKIN AND RESPIRATORY TRACT. CHRONIC:REDNESS OR DRYING OF SKIN;DERMATITIS. Effects of Overexposure:EYES:IRIT;SKIN:IRRIT, POSSIBLE SKIN DISORDERS(DERMATITIS, FOLLICULITIS,OIL ACNE, SKIN CANCER). Medical Cond Aggravated by Exposure:NO DATA AVAILABLE.
======================================
First Aid:INHALE:REM OVE TO FRESH AIR, GIVE CPR/O*2 IF NEED;EYES/SKIN:FLUSH W LG AMTS H*20 FOR 15 MIN;INGEST:RINSE MOUTH; GET MEDICAL ATTENTION FOR EYES, BREATHING DIFFICULTY, OR OTHER SYMPTOMS OF OVEREXPOSURE.
======================================
Flash Point:380F/193C (C-O-C Extinguishing Media:FOAM, CO*2, DRY CHEMICAL Fire Fighting Procedures:KEEP FIRE EXPOSED CONTAINERS COOL WITH WATER SPRAY. Unusual Fire/Explosion Hazard:SULFUR OXIDES,CARBON MONOXIDE.
======= Accidental Release Measures ==========
Spill Release Procedures:RECOVER FREE LIQUID AND ABSORB ON SAND, EARTH ETC.DIKE SPILL AREA.KEEP OUT OF SEWERS, WATERCOURSES.
======================================
Handling and Storage Precautions:STORE IN COOL DRY PLACE. AVOID MIST & VAPORS & PROLONGED SKIN CONTACT.USE MSHA/NIOSH APPROVED RESP EQUIP, IF NECESSARY
Other Precautions:CLEAN CONTAMINATED CLOTHES CLOTHING BEFORE REUSE; USE GOOD PER SONAL HYGIENE.
====== Exposure Controls/Personal Protection =======
Respiratory Protection:NONE NORMALLY REQD. FOR MIST USE APROVED BREATHING EQUIP. Ventilation:AS REQD IF MIST IS GENERATED Protective Gloves:RUBBER Eye Protection:GOGGLES Other Protective Equipment:APROPRIATE CLOTHING TO AVOID SKIN CONTACT Supplemental Safety and Health WASH HANDS/FACE AFTER EACH USE LAUNDER CONTAMINATED CLOTHING BEFORE RE-USE.
========= Physical/Chemical Properties =======
·

=======

Waste Disposal Methods:DISPO SE IN ACCORDANCE W/FED, STATE & LOCAL CODES

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.