

JARVIE PAINT MANUFACTURING CO. -- PRESERVATIVE COATING,CANVAS, TY 1, CL 1 --
8030-00-281-2346

=====
Product Identification
=====

Product ID:PRESERVATIVE COATING,CANVAS, TY 1, CL 1

MSDS Date:01/01/1985

FSC:8030

NIIN:00-281-2346

MSDS Number: BDSSL

=== Responsible Party ===

Company Name:JARVIE PAINT MANUFACTURING CO.

Address:760 ALOHA

City:SEATTLE

State:WA

ZIP:98109-4312

Country:US

CAGE:HO443

=== Co

Contractor Identification ===

Company Name:JARVIE PAINT MANUFACTURING CO.

Address:760 ALOHA STREET

Box:City:SEATTLE

State:WA

ZIP:98019

Phone:206-284-1040

CAGE:HO443

Company Name:JARVIE PAINT MFG CO

Address:760 ALOHA

Box:City:SEATTLE

State:WA

ZIP:98109-4312

Country:US

Phone:206-244-0101

CAGE:3F871

=====
Composition/Information on Ingredients
=====

Ingred Name:COPPER NAPHTHENATE

CAS:1338-02-9

RTECS #:QK9100000

Fraction by Wt: 0.40%

Ingred Name:COPPER QUINOLINOLATE (ACCD TO IARC:

CARCINOGENIC
DETERMINATION: ANIMAL: INDEFINITE)
CAS:10380-28-6
RTECS #:VC5250000
Fraction by Wt: 0.06%

Ingred Name:NAPHTHA (PETROLEUM SPIRITS OR BENZIN)
CAS:8030-30-6
RTECS #:SE7555000
OSHA PEL:100 PPM

Ingred Name:CHLORINATED PARAFFINS

===== Hazards Identification =====

Effects of Overexposure:INH:IRRIT RESP TRACT & MILD
DEPRSSN;DIZZ,NAUSEA,TO CONVUL, & UNCON. SKIN/EYE:PRIMAR IRRIT

===== First Aid Measures =====

=

First Aid:FUMES:REMOVE FROM EXPOSURE, RESTORE BREATHING SKIN:WASH
AFFECTED AREA.

===== Fire Fighting Measures =====

Flash Point:100F TCC
Lower Limits:0.9
Upper Limits:6.0
Extinguishing Media:CO*2, FOAM, DRY CHEMICAL
Fire Fighting Procedures:WATER OR FOAM MAY CAUSE FROTHING.WATER FOG IS
RECOMMENDED.
Unusual Fire/Explosion Hazard:MODERATE FIRE HAZ.ISOLATE FROM ALL
SOURCES OF IGNIT.CLOSED CANS MAY EXPLODE FROM EXTREME HEAT.

===== Accidental Release Measures =====

Spill Release Procedures:REMOVE SPILL W/INERT ABSORBENT & NON-SPARKING
TOOLS.OBSERVE ALL PRECAUTIONAR MEASURES DESCRIBED PREVIOUSLY

===== Handling and Storage =====

Handling and Storage Precautions:AVOID STORING IN HIGH TEMP AREAS. KEEP
AWAY FROM ALL SOURCES OF IGNITION
Other Precautions:AVOID PROLONGED BREATHING OF VAPORS.DO NOT TAKE
INTERNALLY.AVOID PROLONGED CONTACT W/SKIN. DOT:COMBUSTIBLE

=====

==== Exposure Controls/Personal Protection =====

Respiratory Protection:IF ABOVE TLV USE NIOSH/MSHA APPROVED VAPOR MASK

Ventilation:MFG RECM DILUTION VENTILATION;USE LOCAL IF NECESSARY

Protective Gloves:NEOPRENE

Eye Protection:CHEMICAL GOGGLES

Other Protective Equipment:PROTECTIVE OUTERWEAR TO PREVENT CLOTHING
CONTAM & SKIN CNTCT

Supplemental Safety and Health

PRODUCT ALSO CONTAINS 48% PIGMENTS & 32.43% VEHICLE.VAPOR PRESSURE :