View NSN Online: https://aerobasegroup.com/nsn/8010-00-286-9080

CHEMRAY COATINGS CORPORATION -- PAINT, BOOT-TOPPING -- 8010-00-286-9080

Product ID:PAINT, BOOT-TOPPING MSDS Date:01/01/1987 FSC:8010 NIIN:00-286-9080 **MSDS Number: BDTZB** === Responsible Party === Company Name: CHEMRAY COATINGS CORPORATION Address:209 MICHIGAN AVE. City:KENILWORTH State:NJ ZIP:07033 Country:US Emergency Phone Num:201-245-1111 CAGE:OBRN9 === Contrac tor Identification === Company Name: CHEMRAY COATING CORP Address:209 N MICHIGAN AVE Box:City:KENILWORTH State:NJ ZIP:07033 Country:US Phone:201-245-1111 CAGE:33832 Company Name: CHEMRAY COATINGS CORP. Address:209 N. MICHIGAN AVE. Box:NA City:KENILWORTH State:NJ ZIP:07033 Country:US Phone:800-924-9300 CAGE:OBRN9

Ingred Name:PIGMENTS Fraction by Wt: 33%

Ingred Name:ALKYD RESIN Fraction by Wt: 51%

Ingred Name: MINERAL SPIRITS 66

Fraction by Wt: 13% ACGIH TLV:120 PPM

Ingred Name:LEAD COBALT DRIERS (OSHA PEL FROM 29CFR 1910.1025) OSHA PEL:0.05 MG/M3 (PB) ACGIH TLV:0.15 MG/M3(PB); 8990

Ingred Name:ZINC CHROMATE CAS:13530-65-9 RTECS #:GB3290000 Fraction by Wt: 11% OSHA PEL:0.1 MG/M3 (CRO3) ACGIH TLV:0.01MG/M3(CR)A1;9192

	Hazards Identification	
--	------------------------	--

Effects of Overexposure:EXCESSV INHAL MAY CAUSE HEADACH,DIZZ,UNCONSCIOUSNES.OR COMA.SKIN/EYE CONTCT:IRRIT, DRY OF SKIN.

====

First Aid:FUMES:REMOV FROM EXPOSR,RESTORE BREATHING.KEEP WARM. NOTIFY PHYSICIAN.SPLASH(EYES):FLUSH W/RUNNING WATER AT 15 MIN.TAKE TO DR.REMOV CONTAM CLOTHING.CONSULT PHYSICIAN.SPLASH(SKIN):WASH AFFECTED AREA W/ SOAP & WATER.

Flash Point:100F/38C PMCC Extinguishing Media:CO*2,DRY CHEMICAL OR FOAM Fire Fighting Procedures:WATR FOG MAY BE USED TO COOL CLOS CONTNRS TO PRVNT PRESSR(SU Unusual Fire/Explosion Hazard:CLOS CONTNRS MAY EXPLOD WHN EXPOSED TO EXTREME HEAT.DO NOT APPLY TO HOT SURFACES.

Spill Release Procedures:REMOV W/ABSORBENT MATERIAL, FLUSH W/WATER INTO RETAINING AREA OR CONTAINER.AVOID SPARKS, FIRE & HOT SURFACES. VENTILATE AREA.

Handling and Storage Precautions: KEEP AWAY FR HEA

T,SPARKS,OR OPEN

FLAME. USE WITH ADEQUATE VENTILATION.AVOID PROLONGED OR REPEATED CONTACT WITH SKIN.

Other Precautions: DO NOT TAKE INTERNALLY.

====== Exposure Controls/Personal Protection ==========

Respiratory Protection:WHN SPRAYING USE NIOSH & MESA APPRVD. Ventilation:LOC EXHAUST-SUFF.TO KP LEL & LOWST TLV BELO STATED LIMIT.(SU Protective Gloves:F/PRLNG/REPEATD Eye Protection:GOGGLES-SPLASH OR SPRAY Other Protective Equipment:IMPERMEABLE APRON F/PROLNG OR REPEATED

CONTACT.

Supplemental Safety and Health

SPEC.FIRE FIGHT:BUILD UP & AUTO IGNITION WHEN EXPOS TO EXTREME HEAT.WEAR SELF-CONTAINED BREATHING APPARATUS. VENTILAT:MECH-FANS USING EXPLOSION PROOF MOTORS ONLY.

HCC:F4

Boiling Pt:B.P. Text:315-390 Spec Gravity:1.16 Evaporation Rate & amp; Reference:N-BUAC .1 Solubility in Water:NEGLIGIBLE Appearance and Odor:BLACK LIQUID,NOT OBNOXIOUS Percent Volatiles by Volume:58

Stability Indicator/Materials to Avoid:YES STRONG OXIDIZING AGENTS,STRONG ACIDS OR BASES Stability Condition to Avoid:HEAT,SPARKS,OPEN FLAME & FIRE. Hazardous Decomposition Products:THERMAL DECOMP.MAY YIELD CARBON MONOXIDE AND/OR CARBON DIOXI

Waste Disposal Methods: INCINERATE IN APPROVED FACILITY OR DISPOSE OF IAW LOC, STATE & FEDERAL REGULATIONS.DO NOT INCINER

ATE.CLOSED CONTAINERS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their

particular situation.