

DOW CORNING CORPORATION -- DOW CORNING(R) M GEAR OIL ADDITIVE -- 9150-00-390-5690
===== Product Identification =====

Product ID:DOW CORNING(R) M GEAR OIL ADDITIVE

MSDS Date:06/06/1990

FSC:9150

NIIN:00-390-5690

MSDS Number: BDXKJ

=== Responsible Party ===

Company Name:DOW CORNING CORPORATION

Address:SOUTH SAGINAW ROAD

City:MIDLAND

State:MI

ZIP:48686

Country:US

Info Phone Num:517-496-6000

Emergency

Phone Num:(517) 496-5900

Preparer's Name:JACK L. SHENEBERGER

CAGE:5D028

=== Contractor Identification ===

Company Name:DOW CORNING CORP

Address:3901 S SAGINAW RD

Box:997

City:MIDLAND

State:MI

ZIP:48686-0997

Country:US

Phone:517-496-6000/517-496-6315

CAGE:5D028

Company Name:DOW CORNING CORP

Address:2200 W SALZBURG RD

Box:City:AUBURN

State:MI

ZIP:48611

Country:US

Phone:517-496-4388

CAGE:71984

===== Composition/Information on Ingredients =====

Ingred Name:MOLYBDENUM DISULFIDE

C

AS:1317-33-5
RTECS #:QA4697000
Fraction by Wt: 10%
OSHA PEL:10 MG/M3 TDUST (MO)
ACGIH TLV:10 MG/M3 (MO); 8990

Ingred Name:MINERAL OIL (EXPOSURE REGULATED AS 'OIL MIST')
CAS:8012-95-1
RTECS #:PY8030000
Fraction by Wt: 80%
OSHA PEL:5 MG/M3
ACGIH TLV:5 MG/M3/10 STEL;9192

Ingred Name:METHYL METHACRYLATE (SARA III)
CAS:80-62-6
RTECS #:OZ5075000
Fraction by Wt: 10%
OSHA PEL:100 PPM
ACGIH TLV:100 PPM; 9192
EPA Rpt Qty:1000 LBS
DOT Rpt Qty:1000 LBS

Ingred Name:ADDITIVES (TRACE AMOUNTS)

=====
===== Hazards Identification =====

Effects of Overexposure:IRRITATES SKIN AND EYES

===== First Aid Measures =====

First Aid:FLUSH WITH WATER.OBTAIN MEDICAL ATTENTION IF NECESSARY

===== Fire Fighting Measures =====

Flash Point Method:CC
Flash Point:>212F,>106C
Extinguishing Media:WATER FOG, CO*2, DRY CHEMICAL, FOAM.
Fire Fighting Procedures:NIOSH/MSHA APPROVED SCBA & FULL PROTECTIVE
CLOTHING SHO

ULD BE WORN IN FIGHTING FIRES INVOLVING CHEMICALS.
Unusual Fire/Explosion Hazard:HAZARDOUS SULFUR OXIDES FORM.

===== Accidental Release Measures =====

Spill Release Procedures:MOP,WIPE OR SOAK WITH ABSORBENT MATERIAL

===== Handling and Storage =====

Handling and Storage Precautions:USE REASONABLE CARE.AVOID SKIN & EYE CONTACT

===== Exposure Controls/Personal Protection =====

Ventilation:MECHANICAL-YES

Prot

ective Gloves:RBBR OR PLASTIC

Eye Protection:SAFETY GLASSES

Other Protective Equipment:AS REQUIRED

Supplemental Safety and Health

VAPOR PRESS: