View NSN Online: https://aerobasegroup.com/nsn/3439-00-528-3882

Product ID: EASY FLO AWS SPEC. A5.8, BAG-LA, BRAZING METL MSDS Date:01/01/1987 FSC:3439 NIIN:00-528-3882 **MSDS Number: BFCZB** === Responsible Party === **Company Name: HANDY AND HARMON** Emergency Phone Num:212-752-3400 CAGE:LO525 === Contractor Identification === Company Name: HANDY & HARM AN Address:850 THIRD AVENUE Box:City:NEW YORK State:NY ZIP:10022 Country:US Phone:212-752-3400 CAGE:73977 **Company Name: HANDY AND HARMON** CAGE:LO525

Ingred Name:SILVER (SARA III) CAS:7440-22-4 RTECS #:VW3500000 Fraction by Wt: 50.0% OSHA PEL:0.01 MG/M3 ACGIH TLV:0.1 MG/M3; 9192 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB

Ingred Name:COPPER (SARA III) CAS:7440-50-8 RTECS #:GL5325000 Fraction by Wt: 15.5% OSHA PEL:0.1MG/M3 FUME/1 DUST A CGIH TLV:0.2MG/M3 FUME; 9192 EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:ZINC (SARA III) CAS:7440-66-6 RTECS #:ZG8600000 Fraction by Wt: 16.5% OSHA PEL:10 MG ZNO/M3 ACGIH TLV:10 MG ZNO/M3; 9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

Ingred Name:CADMIUM (SARA III) CAS:7440-43-9 RTECS #:EU9800000 Fraction by Wt: 18.0% OSHA PEL:SEE 1910.1027 ACGIH TLV:0.01 MG/M3 DUST;9394 EPA Rpt Qty:10 LBS DOT Rpt Qty:10 LBS

Ef

fects of Overexposure:INHAL;IRRITATION OF NOSE,THROAT,LUNG INFLAMMATION.SEVERE CHEST PAIN,HEADACHE,CHILLS,NAUSE.SEE SUPP D

First Aid:INHALE:REMOVE TO FRESH AIR, GIVE CPR/O\*2 IF NEED;EYES/SKIN:FLUSH W LG AMTS H\*20 FOR 15 MIN;INGEST:RINSE MOUTH; GET MEDICAL ATTENTION FOR EYES, BREATHING DIFFICULTY, OR OTHER SYMPTOMS OF OVEREXPOSURE.

Spill Rele

ase Procedures: USE PERSONAL PROTECTIVE CLOTHING AND GOOD INDUSTRIAL HYGIENE PRACTICE.FOLLOW MFR GUIDE LINE IF NEEDED.

Handling and Storage Precautions:NORMAL PROCEDURES.AVOID HEATING ABOVE BRAZING TEMPERATURE (1175-1375F)METAL DUST MAY CAUSE RESPIRATORY PROBLEM.

Other Precautions: DO NOT BREATH VAPOR. AVOID SKIN AND EYES CONTACT.

======= Exposure Controls/Personal Protection ===============

**Respiratory Protec** 

tion:IF EXPOSD TLV,NIOSH/MESA APPR SELF-CNTND BRTHG APP (POS PR MODE) Ventilation:LOCAL EXHAUST TO MAINTN BELOW TLV. Protective Gloves:LEATHER WELDING Eye Protection:GOGGLES/FACE SHIELD Other Protective Equipment:FULL PROTECTIVE CLOTHING,SAFETY SHOWER,EYE WASH STATION Supplemental Safety and Health MSDS DATED 10/2/84.EFFECT OF OVER-EXP:VOMITING,DIARRHEA.COUGH,G.I.DISTURBANCES,FEVER,DEATH MAY RESULT AFTERLONG TERM EXPOSURE:EYES:IRRITATION,INGEST:CHOKING,VOMITING.CADIUM CAUSES BIRTH DEFECT

HCC:N1 Spec Gravity:9.45 Appearance and Odor:METALLIC ROD,WIRE,STRIP,OR POWDER.

Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid:STABLE AT ROOM TEMPERATURE Hazardous Decomposition Products:ZNO,AG,CU AND (DO FUMES DURING BRAZING Conditions to Avoid Polymerization:AVOID OVERHEATING (ABOVE 1375F)

Waste Disposal Methods:CONSULT THE LOCAL AUTHORITIES.DISPOSAL MUST BE IAW LOCAL,STATE AND FEDERAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.