

HEXCEL CORPORATION;CHEMICAL PRODUCTS DIVISION -- EPOLITE 4015 -- 5970-00-810-1513  
===== Product Identification =====

Product ID:EPOLITE 4015

MSDS Date:06/29/1989

FSC:5970

NIIN:00-810-1513

Kit Part:Y

MSDS Number: BFQHJ

=== Responsible Party ===

Company Name:HEXCEL CORPORATION;CHEMICAL PRODUCTS DIVISION

Address:20701-NORDHOFF STREET

Box:2197

City:CHATSWORTH

State:CA

ZIP:91311-5924

Country:US

Info P

hone Num:800-433-5072 OR 800-367-7527 IN CAL

Emergency Phone Num:818-882-3022, OR 805-498-1399

Preparer's Name:P.W. CUTHBERT

CAGE:01490

=== Contractor Identification ===

Company Name:HEXCEL CORPORATION;CHEMICAL PRODUCTS DIVISION

Address:20701-NORDHOFF STREET

Box:2197

City:CHATSWORTH

State:CA

ZIP:91311-5924

Country:US

Phone:818-882-3022

CAGE:01490

===== Composition/Information on Ingredients =====

Ingred Name:BISPHENOL A, MIXED DIGLYCIDL ETHERS OF.....

CAS:25086-38-6

Fraction

by Wt: 88-98%

Other REC Limits:NONE SPECIFIED

Ingred Name:ALIPHATIC GLYCIDYL ETHER

CAS:68609-97-2

Fraction by Wt: 2-10%

Other REC Limits:NONE SPECIFIED

=====  
===== Hazards Identification =====

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES

Health Hazards Acute and Chronic:ACUTE:IRRITATION,SENSITIZATION

CHRONIC:DERMATITIS IN SENSITIVE PERSON.

Medical Cond Aggravated by Exposure:PRE-EXISTING CONDITIONS MAY BE  
WORSEN

=====  
===== First

Aid Measures =====

First Aid:EYE;FLUSH W/COPIOUS AMOUNT OF WATER;SKIN:WASH WITH SOAP &  
WATER;INHALE:REMOVE TO FRESH AIR,GIVE ARTIFICIAL RESPIRATION IF  
NEEDED;INGEST:SEEK MEDICAL AID.INDUCE VOMITING ONLY ON THE ADVICE  
OF A PHYSIC IAN.

=====  
===== Fire Fighting Measures =====

Flash Point Method:COC

Flash Point:310F,154C

Extinguishing Media:USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY  
CHEMICAL.

Fire Fighting Procedures:FIRE FIGHTERS

SHOULD USE NIOSH APPROVED SCBA &

FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER  
SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE.

Unusual Fire/Explosion Hazard:FIRE OR EXCESSIVE HEAT MAY CAUSE

PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS SUCH AS SMOKE,  
CARBON MONO & DIOXIDES.

=====  
===== Accidental Release Measures =====

Spill Release Procedures:ABSORB SPILL W/INERT MATL. WASH AWAY RESIDUE  
W/DETERGENT & WATER.

=====

Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL DRY AREA AWAY FM OPEN  
FLAME. KEEP CONTAINER CLOSED WHEN NOT IN USE. PROTECT FM DAMMAGE.  
Other Precautions:AVOID CONTACT W/SKIN, EYES, OR CLOTHING.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:USE NIOSH.MSHA APPROVED RESPIRATOR FOR ORGANIC  
VAPORS.MIST IF CONCENTRATION IS HIGH OR NO VENTILATION.  
Ventilation:MECHANICAL RECOMMENDED  
Protective Gloves:CO  
T LINED RUBBR  
Eye Protection:GOGGLES/FACE SHIELD  
Other Protective Equipment:RUBBER APRONS  
Work Hygienic Practices:AVOID CONTACT WITH EYES AND SKIN;DO NOT USE  
CONTAMINATED CLOTHES:WASH AFTER EACH USE.DO NOT EAT,DRINK OR SMOKE  
IN WORK A  
Supplemental Safety and Health  
MSDS DATE REVISED:JUNE 13,1986;THIS DESCRIBES PART A OF TWO PART  
KIT;SEE PART INDICATOR B (RESIN).KEY1:C2.

===== Physical/Chemical Properties =====

HCC:N1  
Vapor Pres: