

AXEL ELECTRONICS INC. -- 6B191 -- 5915-00-856-1302

=====
Product Identification
=====

Product ID:6B191

MSDS Date:01/01/1985

FSC:5915

NIIN:00-856-1302

MSDS Number: BFSXT

=== Responsible Party ===

Company Name:AXEL ELECTRONICS INC.

Address:134-20 JAMAICA AVE

City:JAMAICA

State:NY

ZIP:11418-2619

Country:US

Emergency Phone Num:NONE

CAGE:13058

=== Contractor Identification ===

Company Name:AXEL ELECTR

ONICS INC A UNIT OF GENERAL SIGNAL CORP

Address:134-20 JAMAICA AVE

Box:City:JAMAICA

State:NY

ZIP:11418-2619

Country:US

Phone:718-291-3900

CAGE:13058

=====
Composition/Information on Ingredients
=====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)

CAS:1336-36-3

RTECS #:TQ1350000

EPA Rpt Qty:1 LB

DOT Rpt Qty:1 LB

=====
Hazards Identification
=====

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES
CANCER,LIVER,KID

NEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

=====
===== First Aid Measures =====

First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.

=====
===== Accidental Release Measures =====

Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT RUNOFF.I SOLATE & NOTIFY PROPER AUTHORITIES.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
Ventilation:LOCAL EXHAUST
Protective Gloves:RUBBER-IMPERV
Eye Protection:GOGGLES,FACE SHIELD
Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT
Supplemental Safety and Health
OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.

=====
===== Physical/Chemical Properties =====

HCC:Z3
Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR

=====
===== Stability and Reactivity Data =====

STRONG OXIDIZERS

=====
===== Disposal Considerations =====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINERATION.ONLY APPROVED

DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.