

G AND W ELECTRIC CO -- NOVOID X -- 5970-00-905-6769

=====  
Product Identification  
=====

Product ID:NOVOID X  
MSDS Date:01/01/1987  
FSC:5970  
NIIN:00-905-6769  
MSDS Number: BFVXM  
=== Responsible Party ===  
Company Name:G AND W ELECTRIC CO  
Address:3500 WEST 127TH ST  
City:BLUE ISLAND  
State:IL  
ZIP:60406-1864  
Country:US  
Info Phone Num:708-388-5010  
Emergency Phone Num:708-388-5010  
CAGE:23847  
=== Contractor I  
dentification ===  
Company Name:BECKER JOHN A CO  
Address:1341 EAST 4TH ST  
Box:City:DAYTON  
State:OH  
ZIP:45402-2235  
Country:US  
Phone:513-226-1341  
CAGE:12497  
Company Name:G AND W ELECTRIC CO  
Address:3500 WEST 127TH ST  
Box:City:BLUE ISLAND  
State:IL  
ZIP:60406-1864  
Country:US  
Phone:708-388-5010  
CAGE:23847

=====  
Composition/Information on Ingredients  
=====

Ingred Name:WOOD RESIN

Ingred Name:CASTOR OIL  
RTECS #:FI4100000

=====  
Hazards Identification  
=====

=====

Effects of Overexposure:NONE NOTED BY MFR. LOW TOXICITY & LOW HAZARD TO HEALTH.

===== First Aid Measures =====

First Aid:REMOVE TO FRESH AIR. GIVE CPR/OXYGEN IF NEED. SKIN:WASH WITH SOAP & WATER. EYES:FLUSH WITH WATER 15 MIN. KEEP WARM AND QUIET !

===== Fire Fighting Measures =====

Flash Point:450F/232C (COC)  
Extinguishing Media:CO\*2, FOAM, DRY CHEM.  
Fire Fighting Procedures:WEAR SELF-CNTD BRTHG, APP H\*20 SPRAY TO COOL CONTR.  
Unusual Fire/Explosion Hazard:NONE NOTED BY MANUFACTURER.

===== Accidental Release Measures =====

Spill Release Procedures:WEAR PROTECTIVE GLOVES. COLLECT THE COMPOUND & PLACE IN SALVAGE CONTAINER.

===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL,DRY,WELL VENTILATED AREA. PROTECT FROM PHYSICAL DAMAGE.AVOID ANY PHYSICAL CONTACT. KEEP CONTAINERS TIGHTLY CLOSED  
Other Precautions:NOT KNOWN

===== Exposure Controls/Personal Protection =====

Respiratory Protection:WEAR ORGANIC VAPOR TYPE IF NEEDED.  
Ventilation:NORMAL ROOM VENTILATION.  
Protective Gloves:CANVASS  
Eye Protection:SAFETY GLASSES  
Other Protective Equipment:NORMAL WORK CLOTHINGS.  
Supplemental Safety and Health  
MSDS FROW G & W COMPANY NOT DATED.

===== Physical/Chemical Properties =====

HCC:N1  
Spec Gravity:1.145  
Solubility in Water:NEGLIGIBLE  
Ap

pearance and Odor:DARK BROWN RESINOUS SOLID

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

NOT KNOWN

Stability Condition to Avoid:NONE

Hazardous Decomposition Products:INCOMPLETELY BURNED CARBON PRODUCTS,  
CO\*2, CO.

===== Disposal Considerations =====

Waste Disposal Methods:KEEP IN COVERED DRUMS,PENDING DISPOSAL. HANDLE &  
DISPOSE IN FULL COMPLIANCE WITH ALL APPLICABLE  
INTERNATIONAL,FEDE  
RAL,STATE, & LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):  
This information is formulated for use by elements of the Department  
of Defense. The United States of America in no manner whatsoever,  
expressly or implied, warrants this information to be accurate and  
disclaims all liability for its use. Any person utilizing this  
document should seek competent professional advice to verify and  
assume responsibility for the suitability of this informa  
tion to their  
particular situation.