View NSN Online: https://aerobasegroup.com/nsn/5970-01-009-2775

ROGERS CORPORATION -- RX 3-1-525F END CAP INSULATOR -- 5970-01-009-2775

Product ID:RX 3-1-525F END CAP INSULATOR MSDS Date:01/01/1987 FSC:5970 NIIN:01-009-2775 MSDS Number: BGCZJ === Responsible Party === Company Name: ROGERS CORPORATION Emergency Phone Num:203-646-5500 CAGE:MO501 === Contractor Identification === Company Name: ROGERS CORP MOLDING MATERIALS DIVISI ON Address: MILL AND OAKLAND STS Box:550 **City:MANCHESTER** State:CT ZIP:06040-2316 Country:US CAGE:77897 Company Name: ROGERS CORPORATION CAGE:MO501

Ingred Name:SILICA, CRYSTALLINE - QUARTZ CAS:14808-60-7 RTECS #:VV7330000 Fraction by Wt: 40%. OSHA PEL:SEE TABLE Z3 ACGIH TLV:0.1 MG/M3 RDUST;9293

Ingred Name:ANTIMONY TRIOXIDE (SARA III) CAS:1309-64-4 RTECS #:CC5650000 Fraction by Wt: 5.0% OSHA PEL:0.5 MG/M3 (SB) ACGIH TLV:0.5 MG SB/M3; 9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS

======================================
Effects of Overexposure:EYE,SKN:IRRT. INHL:MILD IRRT INGEST:NONE REPORTED.
======================================
First Aid:EYE:FLUSH 15 MIN W/AMPLE WATER.SKN: WASH SOAP & WATER.INHL:REMOVE TO FRESH AIR. CALL PHYSICIAN IF SYMPTOMS PERSIST.
======================================
Extinguishing Media:WAT ER,FOAM,CO*2, DRY CHEMICAL. Fire Fighting Procedures:USE SCBA AS REQD Unusual Fire/Explosion Hazard:NONE
======================================
Spill Release Procedures:NO SPECIAL REQUIREM
======================================
Handling and Storage Precautions: AVOID ROUGH HANDING & FABRICATION PRACTICES WHICH CREATE DUST.
======================================
Respiratory Protection:USE DUST ASK AS R EQD Ventilation:LOCAL Protective Gloves:IMPERVIOUS Eye Protection:SAFETY GLASSES, SIDE SHLD Other Protective Equipment:WEAR FLL BOD PROTECTION AGAINST DUST. Supplemental Safety and Health MSDS DTD SEP84
======================================
HCC:N1 Spec Gravity:NEG Appearance and Odor:GRANULAR PIOMENTED MATERIAL DISTINCTIVE ODOR Percent Volatiles by Volume:1.88
======================================
Stability Indicator/Materials to A

void:YES NONE Stability Condition to Avoid:ANY DUST CREATING SITUATION. Hazardous Decomposition Products:CARBON OXIDES, HYDROGEN BROMIDES, ACID FUMES.

Waste Disposal Methods:LANDFLL IAW ALL LAWS & REGS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly o

r implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.