View NSN Online: https://aerobasegroup.com/nsn/5970-01-013-9118

Product ID:MAGNOBOND 3901,A & B

MSDS Date:03/16/1989

FSC:5970

NIIN:01-013-9118

MSDS Number: BGDJY === Responsible Party ===

Company Name: MAGNOLIA PLASTICS INC Address: 5547 PEACHTREE INDUSTRIAL BLVD

City: CHAMBLEE

State:GA

ZIP:30341-2234 Country:US

Info Phone Num:404-541-2777 Emergency Phone Num:404

-451-2777 CAGE:22121

=== Contractor Identification ===

Company Name: MAGNOLIA PLASTICS INC Address: 5547 PEACHTREE INDUSTRIAL BLVD

Box:City:CHAMBLEE

State:GA

ZIP:30341-2234 Country:US

Phone: (770) 451-2777/(800) 457-4280

CAGE:22121

====== Composition/Information on Ingredients ========

Ingred Name: METHYL ISOBUTYL KETONE (SARA III)

CAS:108-10-1

RTECS #:SA9275000

= Wt:42.

OSHA PEL:100 PPM/75 STEL ACGIH TLV:50 PPM/75 STEL; 9293

EPA Rpt Qty:5000 LBS DOT Rpt Qty:5000 LBS

Ingred Name:XY

LENES (O-,M-,P- ISOMERS) (SARA III) CAS:1330-20-7 RTECS #:ZE2100000 = Wt:16.OSHA PEL:100 PPM/150 STEL ACGIH TLV:100 PPM/150STEL;9192 EPA Rpt Qty:1000 LBS DOT Rpt Qty:1000 LBS ============= Hazards Identification ======================== Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:ACUTE:IRRITATION OF EYES, SKIN, RESPIRATORY OR G.I. TRACTS; CNS EFFECTS LIKE HEADACHE, DIZZINESS, NAUSEA AMD VOMITING. CHRONIC: DRYING OF SKIN, DEFATTING OR DERMATITIS OR SENSITIZATION. Explanation of Carcinogenicity: DATA PER MSDS Effects of Overexposure: SEE HEALTH HAZARDS DATA. Medical Cond Aggravated by Exposure: PERSONS WITH A HISTORY OF AILMENTS OR WITH A PRE-EXISTING DISEASE INVOLVING THE EYES, SKIN, OR RESPIRATORY TRACT MAY BE AT INCREASED RISK FROM EXPOSURE. First Aid:INHALATION:REMOVE TO FRESH AIR. RESUSCITATE IF N OT BREATHING. GET MEDICAL ATTENTION. EYES: IMMEDIATELY FLUSH WITH PLENTY OF WATER FOR 15 MINUTES HOLDING EYELIDS OPEN. GET MEDICAL ATTENTION. SKIN:REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. IF IRRITATION PERSISTS, GET MEDICAL ADVICE. INGESTION:DO NOT INDUCE VOMITING. GIVE NOTHING BY MOUTH IF UNCONSCIOUS. GET IMMEDIATE MEDICAL ATTENTION.

========= Fire Fighting Measures ==============

Flash Point Method:TOC Flash Point:73.0F,22.8C

Lower

Limits:1.1
Upper Limits:8.0
Extinguishing Media: USE WATER FOG, CARBON DIOXIDE, FOAM, OR DRY
CHEMICAL. Fire Fighting Procedures:FIRE FIGHTERS SHOULD USE NIOSH APPROVED SCBA &
FULL PROTECTIVE EQUIPMENT WHEN FIGHTING CHEMICAL FIRE. USE WATER
SPRAY TO COOL NEARBY CONTAINERS EXPOSED TO FIRE.
Unusual Fire/Explosion Hazard:AVOID EXTREME HEAT;FIRE OR EXCESSIVE HEAT
MAY CAUSE PRODUCTION OF HAZARDOUS DECOMPOSITION PRODUCTS.
========= Accidental Release Measures =========
===
Spill Release Procedures:USE PROPER PERSONAL PROTECTION;CONTAIN FREE
MATERIAL IF POSSIBLE;USE SUITABLE INERT ABSORBENT MATERIAL AND RECOVER FOR PROPER DISPOSAL IN AN APPROVED CONTAINER.
Neutralizing Agent:NOT APPLICABLE.
Nouticing Agont. No FALL Florible.
======================================
Handling and Storage Precautions:STORE IN A COOL, DRY, WELL VENTILATED
AREA. KEEP CONTAINERS TIGHTLY CLOSED WHEN NOT IN USE. PROTECT
CONTAINERS FROM PHYSICAL DAMAGE.
Other Precautions:DO N
OT TAKE INTERNALLY. DO NOT BREATHE MIST. AVOID
PROLONGED OR REPEATED BREATHING OF VAPOR. AVOID CONTACT WITH EYES. USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING.
USE WITH ADEQUATE VENTILATION. WASH THOROUGHLY AFTER HANDLING.
====== Exposure Controls/Personal Protection ========
Respiratory Protection: USE NIOSH/MSHA APPROVED RESPIRATOR AS REQUIRED IF ABOVE PEL/TLV OR SCBA IN AN ENCLOSED AREA.
Ventilation:LOCAL/GENERAL TO MAINTAIN PEL/TLV.
Protective Gloves:NEOPRENE, NITRILE, OR NATURAL RUBBER
Eye Protection:SAFETY G
OGGLES WITH OPTIONAL FACE SHIELD
Other Protective Equipment: EYE WASH STATION AND SAFETY SHOWER, WORK CLOTHING AND APRON AS REQUIRED.
Work Hygienic Practices:OBSERVE GOOD PERSONAL HYGIENE PRACTICES AND
RECOMMENDED PROCEDURES. DO NOT WEAR CONTAMINATED CLOTHING OR
FOOTWEAR.
Supplemental Safety and Health
AVOID PROLONGED OR REPEATED EXPOSURE. DO NOT GET ON SKIN OR IN EYES. DO
NOT BREATHE VAPORS OR MISTS.

========= Physical/Chemical Properties ==========

HCC:F3 Boi ling Pt:=47.C, 116.6F Vapor Pres:14 Vapor Density:>3.5 Spec Gravity:1.0

Evaporation Rate & Reference: 1.6(N-BUTYL ACETATE=1)

Solubility in Water: NEGLIGIBLE

Appearance and Odor:CLEAR LIQUID;POLY SULFIDE ODOR

Percent Volatiles by Volume:60-65

======== Stability and Reactivity Data ===========

Stability Indicator/Materials to Avoid:YES
STRONG OXIDIZING AGENTS;STRONG ACIDS AND BASES
Stability Condition to Avoid:HIGH TEMPERATURES
Hazardous Decomposition Products:CARBON MONOXIDE,
CARBON DIOXIDE AND
OXIDES OF SULFUR

======= Disposal Considerations ============

Waste Disposal Methods:CONSULT LOCAL AUTHORITIES.DISPOSAL MUST BE MADE IN ACCORDANCE WITH ALL APPLICABLE FEDERAL, STATE AND LOCAL LAWS AND REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or impl

ied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.