View NSN Online: https://aerobasegroup.com/nsn/5805-01-017-5697

Product ID:SCOTCHCAST 4407, PART B MSDS Date:11/13/1985 FSC:5975 NIIN:01-017-5697 Kit Part:Y MSDS Number: BGDSV === Responsible Party === Company Name: 3M COMPANY-TELCOMM PRODUCTS DIVISION Address:3M CENTER City:ST PAUL State:MN ZIP:55144-1000 Country:US Emergency Phone Num:612-73 3-1110 CAGE:55203 === Contractor Identification === Company Name: MINNESOTA MINING AND MFG CO TELCOMM MARKETS DIV Address:3M AUSTIN CTR Box:City:AUSTIN State:TX ZIP:79769-2963 Country:US Phone:800-426-8688 CAGE:55203

Ingred Name:HYDROCARBON POLYOL (WT% RANGE:80-90%) Fraction by Wt: 85%. Other REC Limits:NONE

Ingred Name:PLASTICIZER (WT% RANGE:10-20%) Fraction by Wt: 15%. Other REC Limits:NONE

Ingred Name: ALIPHATIC AMINE (WT%

RANGE:0.1-0.5%) Fraction by Wt: 0.3% Other REC Limits:NONE

LD50 LC50 Mixture:ACUTE ORAL (RAT) LD50 < 5ML/KG Routes of Entry: Inhalation:YES Skin:NO Ingestion:YES Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:LOW ACUTE TOXICITY HAZARD, NO CHRONIC EFFECTS REPORTED. SEE CARCINOGEN NOTE. Effects of Overexposure:EYE:SL IRRT. SKN:SL IRRT. MODERATE TO SEVERE IRRT IF CURED MATERIAL F ORCIBLY REMOVED FROM SKIN. INHL: IRRT, POSS ASTHMA SYMPTOMS. INGEST: GI TRACT IRRT POSSIBLE, POSSIBLE IRREVERSIBLE EFFECT (SEE CARC INOGEN NOTE). Medical Cond Aggravated by Exposure:ANY PRE-EXISTING SENSITIVITY OR ALLERGY IN EXPOSED TISSUE.

First Aid:EYE: FLUSH 15 MIN W/AMPLE WATER. SKIN: REMOVE CONTAMINATED CLOTHING/FOOTWEAR. WASH EXPOSED SKIN W/SOAP & WATER. INHAL: REMOVE VICTIM TO FRESH AIR. INGEST: IF CONSCIOUS, GIVE TWO GLASSES WATER & CALL P HYSICIAN OR POISON CENTER, TRY TO DETERMINE DOSE.

Flash Point Method:TCC Flash Point:>270F/>132C Extinguishing Media:CO*2, FOAM, DRY CHEMICAL Fire Fighting Procedures:NONE Unusual Fire/Explosion Hazard:AVOID EXCESS HEAT & IGNITION SOURCES.

Spill Release Procedures: COLLECT PART B SPILL W/ABSORBENT, PLACE IN

CLOSABLE CONTAINER.

 Handling and Storage Precautions: USE ONLY W ADEQUATE VENTILATION. AVOID EYE/SKN CONTACT. DO NOT INHALE OR INGEST.
Other Precautions: CURED MATERIAL IS DIFFICULT TO REMOVE FROM SKIN. LAUNDER CONTAMINATED CLOTHING BEFORE REUSE.

======= Exposure Controls/Personal Protection ===============

Respiratory Protection:USE CCROV RESPIRATOR Ventilation:LOCAL Protective Gloves:IMPERVIOUS Eye Protection:G OGGLES, SAFETY GLASSES Other Protective Equipment:NONE Supplemental Safety and Health 3M MSDS DOC# 10-3071-7, DTD 13NOV85. 3M ID# IS 80-6100-6040-4.KEY1:N1.

HCC:N1 Vapor Pres:NEG Spec Gravity:1.005 Viscosity:450 CPS Solubility in Water:INSOLUBLE Appearance and Odor:AMBER OILY LIQUID Percent Volatiles by Volume:NEG

Stability Indicator/Materials to Avoid:YES NONE Stability Condition to Avoid:AVOID EXCESS HEAT & IGNITION SOURCES. Hazardous Decomposition Products:CARBON OXIDES, TRACES OF HCN, NITROGEN OXIDES

Waste Disposal Methods:LANDFILL OR INCINERATE IAW ALL LAWS & REGS. CURED RESIN MAY BE LANDFILLED, PART A NOT AN EPA HAZWASTE.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department o

f Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.