View NSN Online: https://aerobasegroup.com/nsn/5910-01-028-1672

CORNELL DUBILIER ELEC DIV OF FED PAC ELEC CO -- SCRG152 -- 5910-01-028-1672

Product ID:SCRG152 MSDS Date:01/01/1985 FSC:5910 NIIN:01-028-1672 MSDS Number: BGFSR === Responsible Party === Company Name: CORNELL DUBILIER ELEC DIV OF FED PAC ELEC CO Address: ONE INTERCHANGE PLZ City:WAYNE State:NJ ZIP:07470 Country:US Emergency Phone Num:201-694-8600 CAGE:09023 === Contractor Identification === Company Name: CORNELL DUBILIER ELEC DIV FED PAC ELEC Address: ONE INTERCHANGE PLZ Box:B-967 **City:WAYNE** State:NJ ZIP:07470 Country:US Phone:201-694-8600 CAGE:09023 Company Name: CORNELL-DUBILIER ELECTRONICS Address: ONE INTERCHANGE PLZ Box:City:WAYNE State:NJ ZIP:07470 Country:US Phone:201-694-8600 CAGE:14655

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III) CAS:1336-36-3 RTECS #:TQ1350000 EPA Rp

======================================
Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)
======================================
First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITIN
G,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.
======================================
Spill Release Procedures: USE ABSORBENT & DIKES TO PREVENT RUNOFF. ISOLATE & NOTIFY PROPER AUTHORITIES.
======================================
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.
======================================
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD
Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT Supplemental Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.
======================================
HCC:Z3 Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR
======================================

STRONG OXID

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH TEMPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and discl

aims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.