

DYNAMOLD INC -- P-702-1, HYDRAZINE DETECTOR PELLETT -- 6665-01-089-4443

=====
Product Identification
=====

Product ID: P-702-1, HYDRAZINE DETECTOR PELLETT

MSDS Date: 01/01/1987

FSC: 6665

NIIN: 01-089-4443

MSDS Number: BGLJX

==== Responsible Party ====

Company Name: DYNAMOLD INC

Address: 2905 SHAMROCK AVE

City: FORT WORTH

State: TX

ZIP: 76107

Country: US

Info Phone Num: 817-335-0862

Emergency Phone Num: 817-335-086

2

CAGE: GO277

==== Contractor Identification ====

Company Name: DYNAMOLD INC

Address: 2905 SHAMROCK AVE

Box: 9617

City: FORT WORTH

State: TX

ZIP: 76107-1314

Country: US

Phone: 817-335-0863/817-335-0862

CAGE: GO277

Company Name: DYNAMOLD SOLVENTS, INC.

Address: 2905 SHAMROCK AVE

Box: 9617

City: FORT WORTH

State: TX

ZIP: 76107

Country: US

Phone: 817-335-0862

CAGE: 30256

Company Name: NO COMPANY NAME LISTED

CAGE: 1V478

=====
Composition/Information on Ingredients
=====

Ingred Name: NO HAZARDOUS COMPONE

NTS PER MANUFACTURER

=====
===== Hazards Identification =====

Health Hazards Acute and Chronic:NONE SPECIFIED BY MANUFACTURER.
Explanation of Carcinogenicity:NONE SPECIFIED BY MANUFACTURER.
Effects of Overexposure:NONE SPECIFIED BY MANUFACTURER.
Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

=====
===== First Aid Measures =====

First Aid:NONE NORMALLY REQUIRED.

=====
===== Fire Fighting Measures ====
=====

Flash Point Method:COC
Flash Point:500F,260C
Extinguishing Media:WATER SPRAY, DRY CHEMICALS, CARBON DIOXIDE.
Fire Fighting Procedures:AS IN ANY FIRE, PREVENT HUMAN EXPOSURE TO
FIRE, SMOKE, FUMES, OR COMBUSTION PRODUCTS.
Unusual Fire/Explosion Hazard:NONE

=====
===== Accidental Release Measures =====

Spill Release Procedures:AS THE PELLET IS PLIABLE CURED RUBBER, NO
SPILLAGE WILL OCCUR.
Neutralizing Agent:NONE SPECIFIED BY MANUFACTURER.

=====
===== Handling and Storage =====

Handling and Storage Precautions:STORE IN COOL, DRY PLACE. AVOID DIRECT
SUNLIGHT AND LEAVE IN PROTECTIVE ENVELOPE UNTIL USE.
Other Precautions:NONE SPECIFIED BY MANUFACTURER.

=====
===== Exposure Controls/Personal Protection =====

Respiratory Protection:NONE NORMALLY REQUIRED.
Ventilation:NORMAL WORK PLACE VENTILATION IS ADEQUATE.
Protective Gloves:WEAR ONLY TO KEEP HANDS FROM BEING DYED.
Eye Protection:NONE NORMALLY

REQUIRED.

Other Protective Equipment:NONE NORMALLY REQUIRED.

Work Hygienic Practices:STANDARD HYGENIC PRACTICES

Supplemental Safety and Health

NONE

===== Physical/Chemical Properties =====

HCC:N1

Vapor Pres: