View NSN Online: https://aerobasegroup.com/nsn/6850-01-263-8430

## MAGNAFLUX CORPORATION -- ZL-55 ZYGLO WATER WASHABLE PENETRANT -- 6850-01-263-8430

Product ID:ZL-55 ZYGLO WATER WASHABLE PENETRANT

MSDS Date:11/13/1985

FSC:6850

NIIN:01-263-8430

MSDS Number: BGRRD === Responsible Party ===

Company Name: MAGNAFLUX CORPORATION

Address:7300 W.LAWRENCE AVENUE

City:CHICAGO

State:IL

ZIP:60656-3504 Country:US

Info Phone Num:312-867-8000

Emergency Phone Num:312-867-8000 Preparer's Name:BRUCE C. GRAHAM

CAGE:37676

=== Contractor Identification ===

Company Name: ILLINOIS TOOL WORKS INC MAGNAFLUX DIV

Address:3624 WEST LAKE AVENUE

Box:City:GLENVIEW

State:IL ZIP:60025 Country:US

Phone:847-657-5300/

CAGE:37676

======= Composition/Information on Ingredients ========

Ingred Name: SECONDARY ETHOXYLATED FATTY ALCOHOLS

CAS:68131-40-8 RTECS #:WZ5200000 Fraction by Wt: 50.0%

Ingred Name: UNIDENTIFIED COMPONENTS

Fraction by Wt: 50

======================================
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:IRRITATES EYES ON LIQUID/VAPOR CONTACT.  Effects of Overey popular INHAL ATION: CALISES DIZZINESS DROWSINESS NAUSEA:
Effects of Overexposure:INHALATION:CAUSES DIZZINESS,DROWSINESS,NAUSEA; SKIN:LIQUID IRRITATES BY DISSOLVING SKIN OIL; EYES:VAPORS/LIQUID CAUSES IRRITATION; INGESTION:MANUFACTURER DIDN'T LIST. Medical Cond Aggravated by Exposure:NOT KNOWN
======================================
First Aid:INHALATION:REMOVE TO FRESH AIR.IF BREATHING IS DIFFICULT,GIVE OXYGEN; SKIN:REMOVE CONTAMINATED CLOTHES.WASH OFF WITH FLOWING WATER.USE SOOTHING LOTION.IF IRRITATION PERSISTS,GET MEDICAL ATTN; EYES:IMM EDIATELY RINSE/FLUSH WITH COPIOUS AMOUNT OF RUNNING WATER AND GET MEDICAL ATTENTION.
======================================
Flash Point Method:PMCC Flash Point:>200F/>93C Extinguishing Media:CARBON DIOXIDE,FOAM Fire Figh ting Procedures:KEEP CONTAINERS COOL WITH WATER SPRAY. Unusual Fire/Explosion Hazard:WHEN INVOLVE IN COMBUSTION,MAY EMIT TOXIC GASES AT OR ABOVE DECOMPOSITION TEMPERATURE.
========= Accidental Release Measures ==========
Spill Release Procedures:REMOVE IGNITION SOURCES.SM QTY:WIPE UP OR MOP UP BUT DO NOT BREATHE VAPORS.PLACE RAGS IN CLOSED DRUMS; LG QTY:WEAR PERSONAL SAFETY EQUIPMENTS.DIKE AREA FAR AHEAD.ABSORB LIQUID WITH COMMERCIAL ABSORBEN T.TRANSFER WASTE MATL IN SALVAGE TANKS.
Neutralizing Agent:NOT KNOWN
=========== Handling and Storage =============
Handling and Storage Precautions:STORE AWAY FROM HEAT SOURCES IN WELL VENTILATED AREA.AVOID AGAINST PHYSICAL DAMAGE TO CONTAINERS.KEEP CONTAINERS TIGHTLY CLOSED.  Other Precautions:DO NOT BREATHE VAPORS.DO NOT SMOKE WHILE USING.DO NOT HEAT ABOVE 130F(54C).AVOID FREQUENT OR PROLONGED SKIN CONTACT.
====== Exposure Controls/Personal Protection =======

Respiratory Protection: USE NIOSH APPROVED RESPIRATOR FOR CONFINED AREAS.

Ventilation: GENERAL ROOM VENTILATION TO KEEP BELOW TLV LIMITS.

Protective Gloves: USE NITRILE RUBBER GLOVES IF NEEDED.

Eye Protection: FULL GOGGLES/SAFETY GLASSES W/SIDESHIELD

Other Protective Equipment: NOT KNOWN

Work Hygienic Practices: WASH OFF PROMPTLY WITH WATER. AVOID SKIN CONTACT.

Supplemental Safety and Health

NSN OF MIL-I-25135D,TYPE I,METHOD A,LEVEL 3;PER QPL-25135-15,MAGNAFLUX CORP.,MAY SUPPLY ONE OF

THE FOLLWOING PENETRANTS FOR TYPE I, METHOD

A,LEVEL 3,NSN:ZL-15A,ZL-55, OR ZL-66A;THIS DATA IS OF ZL-55;PR ODUCT NOT AVAILABLE IN AEROSOL CANS;SEEOTHER P/N IND OF THIS NSN FOR OTHER QUALIFIED ITEMS.

======== Physical/Chemical Properties ============

HCC:N1

Boiling Pt:B.P. Text:>400F/>204C

Vapor Pres:0.3MM@100F

Vapor Density:>1.0 Spec Gravity:1.01

Evaporation Rate & Evaporation Rate & Reference: NEGLIGIBLE Solubility in Water: NEGLIGIBLE (EMULSIFY)
Appearance and Odor: GREEN OILY LIQ

UID

========= Stability and Reactivity Data ===========

Stability Indicator/Materials to Avoid:YES

Stability Condition to Avoid: HEAT, HIGH TEMPERATURES

Hazardous Decomposition Products: EMITS OXIDES OF CARBON AND NITROGEN ON COMBUSTION.

======= Disposal Considerations ============

Waste Disposal Methods:INCINERATE OR DISPOSE OF AS EPA HAZARDOUS WASTE D001 (IGNITABLE WASTE),IN ACCORDANCE WITH ALL APPLICABLE FEDERAL,STATE,LOCAL REGULATIONS;IF LO

## CAL AUTHORITIES DO NOT ALLOW DUMPING RINSINGS DOWN THE SEW ER, PURIFY RINSINGS WITH MAGNAFLUX TREATMENT SYSTEM

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent profes sional advice to verify and assume responsibility for the suitability of this information to their particular situation.