View NSN Online: https://aerobasegroup.com/nsn/6850-01-264-8678

MAGNAFLUX CORPORATION -- SKL-LT SPOTCHECK PENETRANT -- 6850-01-264-8678

Product ID:SKL-LT SPOTCHECK PENETRANT MSDS Date:11/19/1985 FSC:6850 NIIN:01-264-8678 MSDS Number: BGRVD === Responsible Party === **Company Name: MAGNAFLUX CORPORATION** Address:7300 W.LAWRENCE AVENUE City:CHICAGO State:IL ZIP:60656 Country:US Info Phone Num:312-867-8000 **Emergency Phone Num:312-8** 67-8000 Preparer's Name: BRUCE C. GRAHAM (CHEMIST) CAGE:37676 === Contractor Identification === Company Name: ILLINOIS TOOL WORKS INC MAGNAFLUX DIV Address:3624 WEST LAKE AVENUE Box:City:GLENVIEW State:IL ZIP:60025 Country:US Phone:847-657-5300/ CAGE:37676 Ingred Name: DISTILATES (PETROLEUM), CATALYTIC REFORMER FRACTIONATER **RESIDUE, LOW BOILING** CAS:68477-31-6 Fraction by Wt: 35.0% Ingred Name:KEROSENE

CAS:8008-20-6 RTECS #:OA5 500000 Fraction by Wt: 10.0% ACGIH TLV:100MG/CUM

======================================
Health Hazards Acute and Chronic:IRRITATES EYES. Effects of Overexposure:INHALATION:CAUSES DIZZINESS,DROWSINESS,NAUSEA; SKIN:LIQUID IRRITATES BY DISSOLVING SKIN OIL; EYES:VAPORS/LIQUID CAUSES IRRITATION; INGESTION:NOT KNOWN TO MANUFACTURER. Medical Cond Aggravated by Exposure:NOT KNOWN
======================================
First Aid:INHA LATION:REMOVE TO FRESH AIR.IF BREATHING IS DIFFICULT,GIVE OXYGEN; SKIN:REMOVE CONTAMINATED CLOTHES.WASH OFF WITH FLOWING WATER.USE SOOTHING LOTION.IF IRRITATION PERSISTS,GET MEDICAL ATTN; EYES:IMM EDIATELY RINSE/FLUSH WITH COPIOUS AMOUNT OF RUNNING WATER,AND GET MEDICAL ATTENTION.
======================================
Flash Point Method:PMCC Flash Point:170F/76.6C Lower Limits:6.0 Upper Limits:1.0 Extinguishing Media:CARBON DIOXIDE, FOAM Fire Figh
ting Procedures:KEEP CONTAINERS COOL WITH WATER SPRAY. Unusual Fire/Explosion Hazard:WHEN INVOLVE IN COMBUSTION,MAY EMIT TOXIC GASES AT OR ABOVE DECOMPOSITION TEMPERATURE.
======================================
Spill Release Procedures:REMOVE IGNITION SOURCES.SM QTY:WIPE UP OR MOP UP BUT DO NOT BREATHE VAPORS.PLACE RAGS IN CLOSED DRUMS; LG QTY:WEAR PERSONAL SAFETY EQUIPMENTS.DIKE AREA FAR AHEAD.ABSORB LIQUID WITH COMMERCIAL ABSORBEN T.TRANSFER WASTE MATL IN SALVAGE TANKS.
======================================
 Handling and Storage Precautions:STORE AWAY FROM HEAT SOURCES IN WELL VENTILATED AREA.AVOID AGAINST PHYSICAL DAMAGE TO CONTAINERS.KEEP CONTAINERS TIGHTLY CLOSED. Other Precautions:DO NOT BREATHE VAPORS.DO NOT SMOKE WHILE USING.DO NOT HEAT ABOVE 130F(54C).AVOID FREQUENT OR PROLONGED SKIN CONTACT.DO NOT SPRAY INTO FLAMES,ARCS,HOT SURFACES.
========= Exposure Controls/Personal Pro

Respiratory Protection:NOT LISTED BY THE MANUFACTURER Ventilation:ADEQUATE VENTILATION Protective Gloves:NITRILE RUBBER Eye Protection:SAFETY GOGGLES/GLASSES Work Hygienic Practices:WASH HANDS AFTER USE. Supplemental Safety and Health ONE PART PRODUCT;THIS DESCRIBES SKL-LT SPOTCHECK PENETRANT WHICH IS SPECIFIED AS TY II,METH C PROD BY QPL-25135-15 FOR MIL-I-25135,REV D;UNDER SAME TYPE & METH,THE QPL ALSO SPECIFIED OTHER PRODUCTS SU CH AS SKL-HF/S,SKL-HT,SKL-LO ,\$ SKL-WP;SKL-LT(LOW TEMP PENETRANT)NOT

AVAILABLE IN AEROSOL CANS FROM MAGNAFLUX.KEY1:N1.

HCC:N1 Boiling Pt:B.P. Text:410F/210C Vapor Pres:0.5 @ 100F Spec Gravity:0.98 Solubility in Water:NEGLIGIBLE Appearance and Odor:RED LIQUID,SLIGHT ODOR

Stability Indicator/Materials to Avoid:YES OXIDIZERS Stability Condition to Avoid:HEAT,HIGH TEMPERATURES. Hazardo us Decomposition Products:EMITS OXIDES OF CARBON AND NITROGEN.

Waste Disposal Methods:INCINERATE OR DISPOSE OF AS EPA HAZARDOUS WASTE D001 (IGNITABLE WASTE),IN ACCORDANCE WITH ALL APPLICABLE FEDERAL,STATE,LOCAL REGULATIONS.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner

whatsoever,

expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.